

表 4.5 : 驗車中心驗車數字 (2009年10月)  
Table 4.5 : Vehicle Inspections at Vehicle Examination Centres (October 2009)

2009/10

		政府運作的驗車中心 Vehicle Inspections at Government Operated Vehicle Examination Centres																								其他 Others	總計 Total	
		的士 Taxis						巴士 Buses								小巴 Light Buses			貨車 Goods Vehicles			拖車 Trailers						
		電單車 <sup>(1)</sup> Motor Cycles <sup>(1)</sup>	私家車 <sup>(1)</sup> Private Cars <sup>(1)</sup>	新界及 大嶼山 NT & Lantau	市區 Urban	收費錶檢 查 Meter Check	新車 New	專營 Franchised				其他 Others				年檢 Annual		新車 New	年檢 Annual		新車/ 新登記 New / New Registration	年檢 Annual	新車/ 新登記 New / New Registration					
								九巴 KMB	城巴 City- bus	新巴 NWFB	龍運 LWB	新大 嶼山 巴士 NLB	新車/ 新登記 New / New Registration	港鐵巴 士 MTR Bus	公共 Public	私家 Private	新車/ 新登記 New / New Registration		公共 Public	私家 Private				≤16 公噸 Tonnes	>16 公噸 Tonnes			≤16 公噸 Tonnes
<b>A. 為發牌及續牌而進行的檢驗 Vehicle Examination for Licensing &amp; Re-licensing</b>																												
驗車數字 No. of Vehicle Inspections		58	723	241	1 200	1 767	23	524	126	100	24	27	2	24	510	32	24	330	112	10	16	1 041	221	-	14	-	7 149	
首次檢驗 First Inspection	及格 Passed	COR	58	605	235	1 137	1 765	21	313	70	53	15	6	-	12	381	27	23	313	104	8	12	793	214	-	12	-	6 177
	不及格 Failed	COF	-	-	-	-	-	-	-	-	-	-	-	2	-	8	-	-	-	-	-	-	-	-	-	-	-	10
其他檢驗 Other Inspection	覆驗 Re-checks	Spot checks	-	63	3	31	1	-	-	-	-	-	-	-	31	-	1	8	4	1	1	122	4	-	1	-	271	
	突擊檢驗 Spot checks	Frame Checks	-	55	3	32	1	2	24	10	14	2	3	-	3	36	1	-	9	4	1	3	126	3	-	1	-	333
不送檢 Did not Attend	不送檢 Did not Attend	Frame Checks	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1
	不送檢 Did not Attend	Spot checks	-	-	-	-	-	-	-	-	-	-	-	-	5	1	-	1	1	-	-	27	1	-	-	-	-	156
預約數字 No. of Appointments		58	734	241	1 212	1 862	24	524	127	100	24	27	2	24	515	33	24	331	113	10	16	1 068	222	-	14	-	7 305	
暫停牌照 Suspension Orders		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	12	-	-	-	-	-	12
<b>B. 其他檢驗 Other Examination</b>																												
驗車數字 No. of Vehicle Inspections		54	324	-	64	-	-	1	-	1	-	-	-	-	10	-	-	20	-	-	200	-	-	10	-	3	687	
VIO 檢驗 VIO Inspection	及格 Passed	Failed	27	178	-	32	-	-	-	-	-	-	-	-	5	-	-	2	-	-	90	-	-	4	-	-	338	
	不及格 Failed	Did not Attend	2	33	-	7	-	-	-	-	-	-	-	-	-	-	-	-	-	-	6	-	-	-	-	-	48	
警方對涉及意外車輛的檢驗 Police Accident Inspection	不送檢 Did not Attend	Did not Attend	7	82	1	2	-	-	-	-	-	-	-	-	2	-	-	1	-	-	39	-	-	8	-	-	142	
	不送檢 Did not Attend	Did not Attend	18	68	-	25	-	-	1	-	1	-	-	-	3	-	-	8	-	-	30	-	-	2	-	3	159	
警方為執法和控制交通而進行的檢驗 Police Enforcement and Control Inspection		7	45	-	-	-	-	-	-	-	-	-	-	-	2	-	-	10	-	-	74	-	-	4	-	-	142	
預約總數 Total Appointments		61	406	1	66	-	-	1	-	1	-	-	-	-	12	-	-	21	-	-	239	-	-	18	-	3	829	
暫停牌照 Suspension Orders		1	4	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	6	-	-	1	-	-	12	

註： (1) 車輛檢驗祇包括登記前、重行登記及特定的檢驗。

Note : (1) Vehicle examinations only include pre-registration, re-registration and miscellaneous examinations.

COR - 檢驗汽車機械及格證書  
COF - 機動車輛全面檢驗及格證書  
VIO - 車輛檢驗事務處

COR - Certificate of Road-worthiness  
COF - Certificate of Fitness  
VIO - Vehicle Inspection Office

表 4.5 (續)

Table 4.5 (cont'd)

2009/10

			其他驗車中心為續牌而進行的檢驗					
			Vehicle Inspections at Other Centres for Re-licensing					
			私家車 Private Car	輕型貨車 Light Goods Vehicle		中型貨車 Medium Goods Vehicle		拖車 Trailers
少於1.9公噸 <1.9 Tonnes	1.9至5.5公噸 1.9 - 5.5 Tonnes	> 5.5至16公噸 > 5.5 - 16 Tonnes						
<b>A. 新九龍灣驗車中心 New Kowloon Bay Vehicle Examination Centre</b>								
驗車數字 No. of Vehicle Inspections			-	-	5 866	2 623	1 264	9 753
首次檢驗 First Inspection	及格 Passed		-	-	5 120	2 231	1 104	8 455
	不及格 Failed		-	-	239	140	36	415
其他檢驗 Other Inspection	覆驗 Re-checks		-	-	507	252	124	883
不送檢 Did not Attend			-	-	119	63	22	204
預約數字 No. of Appointments			-	-	5 985	2 686	1 286	9 957
暫停牌照 Suspension Orders			-	-	9	12	9	30
<b>B. 指定車輛驗車中心 Designated Car Testing Centre</b>								
驗車數字 No. of Vehicle Inspections			20 121	54	-	-	-	20 175
首次檢驗 First Inspection	及格 Passed		18 537	52	-	-	-	18 589
	不及格 Failed		835	1	-	-	-	836
其他檢驗 Other Inspection	覆驗 Re-checks		749	1	-	-	-	750
不送檢 Did not Attend			-	-	-	-	-	-
預約數字 No. of Appointments			20 121	54	-	-	-	20 175
暫停牌照 Suspension Orders			18	-	-	-	-	18

資料來源：車輛安全及標準部

Source : Vehicle Safety and Standards Division