

表 4.5 : 驗車中心車輛檢驗數字 (二零一二年十一月)  
Table 4.5 : Vehicle Inspections at Vehicle Examination Centres (November 2012)

2012/11

		政府運作的驗車中心 Vehicle Inspections at Government Operated Vehicle Examination Centres																								總計 Total		
		電單車 <sup>(1)</sup> Motor Cycles <sup>(1)</sup>	私家車 <sup>(1)</sup> Private Cars <sup>(1)</sup>	的士 Taxis			巴士 Buses										小巴 Light Buses			貨車 <sup>(2)</sup> Goods Vehicles <sup>(2)</sup>			拖車 Trailers		其他 Others			
				新界及 大嶼山 NT & Lantau	市區 Urban	收費錶 檢查 Meter Check	新車 New	專營 Franchised					其他 Others					年檢 Annual		新車/ 新登記 New / New Registration	年檢 Annual	新車/ 新登記 New / New Registration	年檢 Annual	新車/ 新登記 New / New Registration				
								九巴 KMB	城巴 City- bus	新巴 NWFB	龍運 LWB	新大 嶼山 巴士 NLB	新車/ 新登記 New / New Registration	港鐵 巴士 MTR Buses	公共 Public	私家 Private	新車/ 新登記 New / New Registration	公共 Public	私家 Private								新車 New	≤16 公噸 ≤16 Tonnes
驗車數字 No. of Vehicle Inspections		121	875	274	1 187	1 806	23	311	74	53	11	14	35	14	438	47	54	395	127	44	8	984	396	-	37	-	7 328	
首次檢驗 First Inspection	及格 Passed	COR	120	727	269	1 113	1 801	23	311	74	53	11	10	-	14	386	32	51	358	109	40	8	809	378	-	35	-	6 732
	不及格 Failed	COF	-	-	-	-	-	-	-	-	-	4	35	-	3	7	-	-	-	-	-	-	-	-	-	-	-	49
其他檢驗 Other Inspection	覆驗 Re-checks	COF	-	79	2	38	-	-	-	-	-	-	-	-	25	4	2	19	8	2	-	90	8	-	1	-	278	
	車架檢驗 Frame Checks	COF	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
	不送檢 Did not Attend	COF	2	14	4	7	88	-	-	-	-	-	-	-	15	-	1	1	1	-	-	32	7	-	-	-	172	
	預約數字 No. of Appointments	COF	123	889	278	1 194	1 894	23	311	74	53	11	14	35	14	453	47	55	396	128	44	8	1 016	403	-	37	-	7 500
	暫停牌照 Suspension Orders	COF	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	5	-	-	-	-	6	
<b>B. 其他檢驗 Other Inspection</b>																												
驗車數字 No. of Vehicle Inspections		COF	29	311	3	70	-	-	249	43	56	8	-	-	42	2	-	49	1	-	182	13	-	9	-	8	1 075	
VIO 檢驗	及格 Passed	COF	10	170	1	31	-	-	-	-	-	-	-	-	2	-	-	27	1	-	103	7	-	5	-	-	357	
	不及格 Failed	COF	1	21	-	2	-	-	-	-	-	-	-	-	-	-	-	4	-	-	16	1	-	2	-	-	47	
Inspection	不送檢 Did not Attend	COF	4	80	2	9	-	-	-	-	-	-	-	-	1	-	-	14	-	-	42	4	-	2	-	1	159	
	突擊檢驗 Spot Checks	COF	-	-	-	-	-	247	43	50	8	-	-	-	36	2	-	-	-	-	-	-	-	-	-	-	386	
	警方對涉及意外車輛的檢驗 Police Accident Inspection	COF	13	49	2	33	-	-	2	-	5	-	-	-	2	-	-	6	-	-	30	3	-	1	-	7	153	
	警方為執法和控制交通而進行的檢驗 Police Enforcement and Control Inspection	COF	5	71	-	4	-	-	-	-	1	-	-	-	2	-	-	12	-	-	33	2	-	1	-	1	132	
	預約總數 Total Appointments	COF	33	391	5	79	-	-	249	43	56	8	-	-	43	2	-	63	1	-	224	17	-	11	-	9	1 234	
	暫停牌照 Suspension Orders	COF	2	1	-	1	-	-	-	-	-	-	-	-	3	-	-	1	-	-	2	-	-	1	-	-	11	

註： (1) 車輛檢驗只包括登記前、重行登記及特定的檢驗。  
(2) 二零一二年三月或以前貨車的其他檢驗數字並沒有按貨車種類分項列出。

Notes : (1) Vehicle inspections include pre-registration, re-registration and miscellaneous inspections only.  
(2) For other inspection figures of goods vehicles on or before March 2012, they are not classified by goods vehicle type.

COR - 檢驗汽車機械及格證書  
COF - 機動車輛全面檢驗及格證書  
VIO - 車輛檢驗事務處

COR - Certificate of Road-worthiness  
COF - Certificate of Fitness  
VIO - Vehicle Inspection Office

表 4.5 (續)

Table 4.5 (cont'd)

2012/11

		其他驗車中心為續牌而進行的車輛檢驗 Vehicle Inspections at Other Examination Centres for Re-licensing					
		輕型貨車 Light Goods Vehicles		中型貨車 Medium Goods Vehicles		拖車 Trailers	總計 Total
		少於1.9公噸 <1.9 Tonnes	1.9至5.5公噸 1.9 - 5.5 Tonnes	> 5.5至16公噸 > 5.5 - 16 Tonnes			
私家車 Private Cars							
<b>A. 新九龍灣驗車中心 New Kowloon Bay Vehicle Examination Centre</b>							
驗車數字 No. of Vehicle Inspections		-	-	6 209	2 332	1 221	9 762
首次檢驗 First Inspection	及格 Passed	-	-	5 650	2 066	1 144	8 860
	不及格 Failed	-	-	271	130	39	440
其他檢驗 Other Inspection	覆驗 Re-checks	-	-	288	136	38	462
不送檢 Did not Attend		-	-	161	83	35	279
預約數字 No. of Appointments		-	-	6 370	2 415	1 256	10 041
暫停牌照 Suspension Orders		-	-	10	17	2	29
<b>B. 指定車輛驗車中心 Designated Car Testing Centre</b>							
驗車數字 No. of Vehicle Inspections		24 400	33	-	-	-	24 433
首次檢驗 First Inspection	及格 Passed	20 839	27	-	-	-	20 866
	不及格 Failed	1 877	4	-	-	-	1 881
其他檢驗 Other Inspection	覆驗 Re-checks	1 684	2	-	-	-	1 686
不送檢 Did not Attend		-	-	-	-	-	-
預約數字 No. of Appointments		24 400	33	-	-	-	24 433
暫停牌照 Suspension Orders		-	-	-	-	-	-

資料來源：車輛安全及標準部

Source : Vehicle Safety and Standards Division