

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000290

製造商 Make: 日產 Nissan

型號 Model: Tiida C11, SC11

項目 Subject: 檢查轉向萬向節

Inspection of Steering Lower Joint

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

<b>C11</b>	
1	<b>C11-980203</b>
2	<b>C11-980204</b>
3	<b>C11-980205</b>
4	<b>C11-980206</b>
5	<b>C11-980207</b>
6	<b>C11-980208</b>
7	<b>C11-980209</b>
8	<b>C11-980210</b>
9	<b>C11-980211</b>
10	<b>C11-980212</b>
11	<b>C11-980218</b>

12	<b>C11-980219</b>
13	<b>C11-980220</b>
14	<b>C11-980225</b>
15	<b>C11-980226</b>

<b>SC11</b>	
1	<b>SC11-990119</b>
2	<b>SC11-990120</b>
3	<b>SC11-990121</b>
4	<b>SC11-990122</b>
5	<b>SC11-990128</b>
6	<b>SC11-990130</b>