

Recall Detail	
<b>Ref No</b>	<b>10000491</b>
<b>Manufacturer</b>	Suzuki Motor Corporation
<b>Vehicle Class</b>	Light Goods Vehicle
<b>Model/Type</b>	EVERY (GE306)
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Inoperative Defroster
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Rain water may ingress to the blower motor due to production defect of the open air intake of the A/C. If use continues under this condition, resistor might be overheated or blower motor might be malfunction.
<b>Remedial Action</b>	Inspection of defroster system, install protective cover, replacement of blower motor and resistor if necessary.
<b>Build Dates</b>	06/08/2005 - 18/03/2010
<b>Launch Date</b>	13/10/2014
<b>Tentative Date of Recall Completion</b>	12/10/2015

1	DA64V131140
2	DA64V131479
3	DA64V139405
4	DA64V139465
5	DA64V139519
6	DA64V140592
7	DA64V141531
8	DA64V143919
9	DA64V145973
10	DA64V146513
11	DA64V147042
12	DA64V150127
13	DA64V150255
14	DA64V154040
15	DA64V154956
16	DA64V155445
17	DA64V155729
18	DA64V156294
19	DA64V160489

20	DA64V160738
21	DA64V161237
22	DA64V161582
23	DA64V161854
24	DA64V161863
25	DA64V164152
26	DA64V164631
27	DA64V165096
28	DA64V165501
29	DA64V165909
30	DA64V166147
31	DA64V166800
32	DA64V166967
33	DA64V167807
34	DA64V168844
35	DA64V168847
36	DA64V169419
37	DA64V170019
38	DA64V170227

39	DA64V170475
40	DA64V171249
41	DA64V171838
42	DA64V172283
43	DA64V172996
44	DA64V177765
45	DA64V179781
46	DA64V180098
47	DA64V181046
48	DA64V181293
49	DA64V181603
50	DA64V186318
51	DA64V186427
52	DA64V189750
53	DA64V189918
54	DA64V190717
55	DA64V191366
56	DA64V191873
57	DA64V192052
58	DA64V193975
59	DA64V194317
60	DA64V196730
61	DA64V197260
62	DA64V198600
63	DA64V198725
64	DA64V199183
65	DA64V199491
66	DA64V200210
67	DA64V200587
68	DA64V201481
69	DA64V202513
70	DA64V203152
71	DA64V204997
72	DA64V205555
73	DA64V214227
74	DA64V246354
75	DA64V249785
76	DA64V250079
77	DA64V250446
78	DA64V252526

79	DA64V253113
80	DA64V253344
81	DA64V253712
82	DA64V254168
83	DA64V254326
84	DA64V254506
85	DA64V254839
86	DA64V255003
87	DA64V257780
88	DA64V257873
89	DA64V258234
90	DA64V258491
91	DA64V258998
92	DA64V259126
93	DA64V260006
94	DA64V261343
95	DA64V261999
96	DA64V262581
97	DA64V263184
98	DA64V263758
99	DA64V264022
100	DA64V264680
101	DA64V265342
102	DA64V275324
103	DA64V276112
104	DA64V279111
105	DA64V279649
106	DA64V291363
107	DA64V291597
108	DA64V291852
109	DA64V293943
110	DA64V294882
111	DA64V295515
112	DA64V295707
113	DA64V295932
114	DA64V298014
115	DA64V301512
116	DA64V301674
117	DA64V302618
118	DA64V303326

119	DA64V311819
120	DA64V312073
121	DA64V312193
122	DA64V312339
123	DA64V312463
124	DA64V312578
125	DA64V312695
126	DA64V312820
127	DA64V312935
128	DA64V313174
129	DA64V313273
130	DA64V313357
131	DA64V313507
132	DA64V313769
133	DA64V313903
134	DA64V314283
135	DA64V314816
136	DA64V315315
137	DA64V315697
138	DA64V327448
139	DA64V328029
140	DA64V330052
141	DA64V330592
142	DA64V331378
143	DA64V365660
144	DA64V365889
145	DA64V371176
146	DA64V371178
147	DA64V371567
148	DA64V371651
149	DA64V372161
150	DA64V375454
151	DA64V378724
152	DA64V380774
153	DA64V381718
154	DA64V382258
155	DA64V382988
156	DA64V385738
157	DA64V386006
158	DA64V386364

159	DA64V386689
160	DA64V387515
161	DA64V389661
162	DA64V390908
163	DA64V392950
164	DA64V393601
165	DA64V393727
166	DA64V394138
167	DA64V394326
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	
195	
196	
197	
198	