

Recall Detail

Ref No	10001192
Manufacturer	ISUZU
Vehicle Class	Commercial vehicle
Model/Type	ISUZU N series
Dealer (phone no)	Triangle Motors Ltd (Tele: 2216 8163)
Subject	ISUZU N Series – Replace Injection Pipe Bracket and Pipe Clip
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to improper production of the injection pipe bracket, interference between an injection pipe and pipe clip may occur. If a vehicle is used in this condition continuously, fuel leaks may occur.
Remedial Action	Replace injection pipe bracket and pipe clip.
Build Dates	2024
Launch Date	09/01/2025
Tentative Date of Recall Completion	08/01/2030

N series

- 1 JAANPR75KR7102252
- 2 JAANPR75KR7102295