

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: CR6W, CR9W

項目 Subject: 安裝儀錶電路板附加電線

Installation of combination meter circuit board sub harness

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
1	JS3608	JMYLECR9W1U000222
2	GC1876	JMYLECR9W1U000667
3	JU2017	JMYLECR9W1U000493
4	KV9583	JMYLECR9W1U000832
5	JX9657	JMYLECR9W1U000845
6	FA8933	JMYLECR9W1U000681
7	KA4056	JMYLECR9W1U000857
8	KB4235	JMYLECR9W1U001026
9	JU1715	JMYLECR9W1U000482
10	FV501	JMYLECR9W1U000512
11	KF8035	JMYLECR9W1U000881
12	JZ766	JMYLECR9W1U000723
13	KV2909	JMYLECR5W2U000263
14	ET377	JMYLECR9W1U000458
15	CX6866	JMYLECR9W1U000867
16	LD7651	JMYLECR9W1U000716
17	GK3178	JMYLECR9W1U000829
18	FG6836	JMYLECR9W1U000798
19	JV9648	JMYLECR9W1U000636
20	JX7926	JMYLECR9W1U000800
21	JU2429	JMYLECR9W1U000539
22	KD2919	JMYLECR9W1U001075
23	KM4727	JMYLECR9W1U001157
24	KM5260	JMYLECR9W1U001161
25	KM5380	JMYLECR9W1U001164
26	KM5450	JMYLECR9W1U001154
27	KM4903	JMYLECR9W1U001159
28	KM4979	JMYLECR9W1U001155
29	KF9354	JMYLECR9W1U001089
30	LE7819	JMYLSCR6W2U000252

	Reg Mark	Chassis Number
31	AV3083	JMYLECR9W1U000605
32	EC3881	JMYLECR9W1U000827
33	KM4507	JMYLECR9W1U001126
34	KM4738	JMYLECR9W1U001127
35	KM4879	JMYLECR9W1U001128
36	KM5009	JMYLECR9W1U001143
37	KM5309	JMYLECR9W1U001132
38	KM5868	JMYLECR9W1U001140
39	KM6111	JMYLECR9W1U001162
40	KM6450	JMYLECR9W1U001121
41	KM654	JMYLECR9W1U001082
42	KM725	JMYLECR9W1U001085
43	KN7408	JMYLECR9W1U001150
44	JZ4248	JMYLECR9W1U000842
45	JR8999	JMYLECR9W1U000720
46	FD9392	JMYLECR9W1U000662
47	JS1729	JMYLECR9W1U000246
48	KK9327	JMYLECR5W2U000215
49	KN8098	JMYLECR9W1U000305
50	JR9337	JMYLECR9W1U000241
51	KS5666	JMYLECR5W2U000233
52	KG8331	JMYLECR9W1U001061
53	JT3611	JMYLECR9W1U000388
54	ME775	JMYLSCR6W2U000278
55	2222	JMYLECR9W1U000671
56	HA7812	JMYLECR9W1U000412
57	MH5396	JMYLECR9W1U000601
58	HM8400	JMYLECR9W1U000621
59	BH180	JMYLECR9W1U000552
60	KR7702	JMYLECR9W1U001183

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: CR6W, CR9W

項目 Subject: 安裝儀錶電路板附加電線

Installation of combination meter circuit board sub harness

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
61	JT4213	JMYLECR9W1U000367
62	GJ250	JMYLECR9W1U000676
63	KM4058	JMYLECR9W1U001146
64	KN7990	JMYLECR9W1U001135
65	GY6882	JMYLECR9W1U000817
66	GJ756	JMYLECR9W1U000231
67	JU2082	JMYLECR9W1U000519
68	LN5708	JMYLECR9W1U000847
69	12546	JMYLECR9W1U000803
70	CL448	JMYLECR9W1U000704
71	LU406	JMYLECR9W1U000665
72		JMYLSCR6W2U000247
73	JT2901	JMYLECR9W1U000354
74	KH3246	JMYLECR9W1U000900
75	JT3339	JMYLECR9W1U000373
76	HZ9228	JMYLECR9W1U000210
77	DD428	JMYLECR9W1U000618
78	GN6200	JMYLECR9W1U001074
79	KB2766	JMYLECR9W1U001024
80	KB3079	JMYLECR9W1U001017
81	KB3457	JMYLECR9W1U001030
82	KB3645	JMYLECR9W1U001020
83	KB4136	JMYLECR9W1U001011
84	KP8362	JMYLECR9W1U000966
85	KB2037	JMYLECR9W1U001009
86	KN2524	JMYLECR9W1U001076
87	FD9099	JMYLECR9W1U000649
88	JU8812	JMYLECR9W1U000679
89	LE7355	JMYLECR9W1U000256
90	FZ3669	JMYLECR9W1U000807

	Reg Mark	Chassis Number
91	CN4328	JMYLECR9W1U000240
92	ES8768	JMYLECR9W1U000498
93	JY8310	JMYLECR9W1U000854
94	KU8848	JMYLECR9W1U001051
95	KF7285	JMYLECR9W1U001083
96	JY3181	JMYLECR9W1U000837
97	DY8018	JMYLECR9W1U000619
98	LB3803	JMYLECR5W2U000252
99	KJ2221	JMYLECR9W1U000596
100	HL809	JMYLECR9W1U000202
101	CP6018	JMYLECR9W1U000630
102	EJ310	JMYLECR9W1U000521
103	JU7688	JMYLECR9W1U000641
104	KP2605	JMYLECR9W1U001052
105	JU6586	JMYLECR9W1U000503
106	LH7060	JMYLECR9W1U000849
107	FZ2519	JMYLECR9W1U000248
108	JU1074	JMYLECR9W1U000459
109	LA1196	JMYLECR9W1U000815
110	JU9909	JMYLECR9W1U000696
111	LN4083	JMYLSCR6W2U000292
112	JK822	JMYLECR9W1U000703
113	JX7644	JMYLECR9W1U000846
114	KS639	JMYLSCR6W2U000201
115	JY1333	JMYLECR9W1U000822
116	ET3303	JMYLECR9W1U000545
117	HR9912	JMYLECR9W1U000547
118	KH5254	JMYLECR9W1U000860
119	KH9982	JMYLECR9W1U000496
120	KP2252	JMYLECR9W1U001063

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: CR6W, CR9W

項目 Subject: 安裝儀錶電路板附加電線

Installation of combination meter circuit board sub harness

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
121	JY124	JMYLECR9W1U000819
122	JU1193	JMYLECR9W1U000463
123	FW867	JMYLECR9W1U000811
124	JT2218	JMYLECR9W1U000409
125	DX3893	JMYLECR9W1U001039
126	JU2416	JMYLECR9W1U000568
127	FC6786	JMYLECR9W1U000400
128	JK6989	JMYLECR9W1U000322
129	HB6025	JMYLECR9W1U000523
130	JW7140	JMYLECR9W1U000708
131	JU7639	JMYLECR9W1U000629
132	LE5563	JMYLECR9W1U000824
133	FN8333	JMYLECR9W1U000417
134	MH-9045	JMYLECR9W1U000263
135	JV5264	JMYLECR9W1U000711
136	LB7296	JMYLECR9W1U000821
137	KY5787	JMYLSCR6W2U000266
138	KN3332	JMYLECR9W1U001066
139	DX9798	JMYLECR9W1U000855
140	KH9132	JMYLECR9W1U000874
141	GU1183	JMYLECR9W1U000620
142	KE2178	JMYLECR9W1U000876
143	JV1130	JMYLECR9W1U000608
144	KP1774	JMYLECR9W1U001067
145	KC1353	JMYLECR9W1U001043
146	KC1816	JMYLECR9W1U001041
147	JV7193	JMYLECR9W1U000677
148		JMYLECR9W1U001087
149	CP5338	JMYLECR9W1U000642
150	GR1368	JMYLECR9W1U000870

	Reg Mark	Chassis Number
151	11923	JMYLECR9W1U000224
152	LD2511	JMYLECR9W1U000607
153	GY2377	JMYLECR9W1U000624
154	EV810	JMYLECR9W1U000536
155	JT4177	JMYLECR9W1U000348
156	JS4963	JMYLECR9W1U000279
157	GU9989	JMYLECR9W1U000203
158	JP1120	JMYLECR9W1U000904
159	KF6577	JMYLECR9W1U001058
160	HF654	JMYLECR9W1U000471
161	JT3700	JMYLECR9W1U000423
162	JU879	JMYLECR9W1U000570
163	AF599	JMYLECR9W1U000660
164	JZ6949	JMYLECR9W1U000938
165	KD4851	JMYLECR9W1U001050
166	KP718	JMYLECR9W1U001173
167	HF249	JMYLECR9W1U000238
168	LG5629	JMYLSCR6W2U000276
169	JU1850	JMYLECR9W1U000529
170	AB1119	JMYLECR9W1U000505
171	GA8211	JMYLECR9W1U000653
172	KB6998	JMYLECR9W1U000875
173	GK3398	JMYLECR9W1U000801
174	KT8274	JMYLECR5W2U000213
175	HF6216	JMYLECR9W1U000647
176	JX6715	JMYLECR9W1U000805
177	KF3227	JMYLECR9W1U000905
178	JS4515	JMYLECR9W1U000247
179	GB7233	JMYLECR9W1U000823
180	DU7020	JMYLECR9W1U000697

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: CR6W, CR9W

項目 Subject: 安裝儀錶電路板附加電線

Installation of combination meter circuit board sub harness

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
181	KG9920	JMYLECR9W1U000475
182	KM2948	JMYLECR9W1U001170
183	KM3917	JMYLECR9W1U001172
184	KY9370	JMYLSCR6W2U000246
185	EN480	JMYLECR9W1U000217
186	KR9482	JMYLECR9W1U000813
187	KT531	JMYLECR9W1U000721
188	GJ8020	JMYLECR9W1U001032
189	HW720	JMYLECR9W1U000861
190	JU2144	JMYLECR9W1U000591
191	HK2887	JMYLECR9W1U000885
192	KV1812	JMYLECR9W1U000301
193	EG5015	JMYLECR9W1U000669
194	KD6918	JMYLECR9W1U001038
195	LA6620	JMYLECR5W2U000255
196	JU8182	JMYLECR9W1U000603
197	EV3083	JMYLECR9W1U000893
198	KJ3085	JMYLECR9W1U000252
199	KL5709	JMYLECR9W1U000895
200	FP8196	JMYLECR9W1U000271
201	FU906	JMYLECR9W1U000897
202	JU1213	JMYLECR9W1U000514
203	HC617	JMYLECR9W1U000230
204	JU8510	JMYLECR9W1U000714
205	ER9620	JMYLECR9W1U000991
206	HW2303	JMYLECR9W1U000260
207	JT4050	JMYLECR9W1U000364
208	JZ6725	JMYLECR9W1U000826
209	JZ6875	JMYLECR9W1U000866
210	JZ7163	JMYLECR9W1U000808

	Reg Mark	Chassis Number
211	JZ7207	JMYLECR9W1U000872
212	JZ7978	JMYLECR9W1U000941
213	KA8676	JMYLECR9W1U001035
214	KA9307	JMYLECR9W1U000889
215	KA9690	JMYLECR9W1U001036
216	KB134	JMYLECR9W1U000997
217	KB396	JMYLECR9W1U000984
218	KB4265	JMYLECR9W1U001003
219	KJ8027	JMYLECR9W1U001044
220	KK7665	JMYLECR9W1U000840
221	KM3281	JMYLECR9W1U001138
222	KM3297	JMYLECR9W1U001171
223	KM3704	JMYLECR9W1U001152
224	KM3807	JMYLECR9W1U001165
225	KM3856	JMYLECR9W1U001151
226	KM3900	JMYLECR9W1U001139
227	KM5136	JMYLECR9W1U001156
228	KM5422	JMYLECR9W1U001129
229	KN5270	JMYLECR9W1U001130
230	KR4057	JMYLECR9W1U001184
231	KR4904	JMYLECR9W1U000898
232	LB5045	JMYLECR9W1U001049
233	7980	JMYLECR9W1U000264
234	245670	JMYLECR9W1U001005
235	BK8337	JMYLECR9W1U000666
236	BZ7813	JMYLECR5W2U000219
237	CA1333	JMYLECR9W1U000692
238	CD117	JMYLECR9W1U000244
239	DD2889	JMYLECR9W1U001059
240	DZ1205	JMYLECR9W1U000848

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: CR6W, CR9W

項目 Subject: 安裝儀錶電路板附加電線

Installation of combination meter circuit board sub harness

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
241	EX7009	JMYLECR9W1U000579
242	EZ9363	JMYLECR9W1U000864
243	FD5852	JMYLECR9W1U000656
244	FD8013	JMYLECR9W1U000363
245	FF4095	JMYLECR9W1U001042
246	FT1108	JMYLECR9W1U000661
247	FW3972	JMYLECR9W1U000637
248	GH8657	JMYLECR9W1U000214
249	HD1908	JMYLECR9W1U000599
250	HK1972	JMYLECR9W1U000347
251	HM2703	JMYLECR9W1U000643
252	JF3581	JMYLECR9W1U000877
253	JR3818	JMYLECR9W1U000341
254	JR4800	JMYLECR9W1U000239
255	JS3028	JMYLECR9W1U000257
256	JS3483	JMYLECR9W1U000267
257	JS3508	JMYLECR9W1U000261
258	JS6851	JMYLECR9W1U000304
259	JT2088	JMYLECR9W1U000659
260	JT2532	JMYLECR9W1U000393
261	JU1428	JMYLECR9W1U000698
262	JU1462	JMYLECR9W1U000573
263	JU1896	JMYLECR9W1U000576
264	JU3546	JMYLECR9W1U000574
265	JU4211	JMYLECR9W1U000595
266	JU725	JMYLECR9W1U000502
267	JU7618	JMYLECR9W1U000650
268	JU7663	JMYLECR9W1U000644
269	JU9154	JMYLECR9W1U000556
270	JV441	JMYLECR9W1U000664

	Reg Mark	Chassis Number
271	JV5207	JMYLECR9W1U000481
272	JV8045	JMYLECR9W1U000648
273	JV8693	JMYLECR9W1U000674
274	JV9447	JMYLECR9W1U000690
275	JX7742	JMYLECR9W1U000851
276	JY7971	JMYLECR9W1U000312
277	JZ3990	JMYLECR9W1U000839
278	JZ7042	JMYLECR9W1U000940
279	JZ7184	JMYLECR9W1U000943
280	JZ7427	JMYLECR9W1U000939
281	JZ7688	JMYLECR9W1U000896
282	JZ7838	JMYLECR9W1U000937
283	JZ7886	JMYLECR9W1U000806
284	JZ8187	JMYLECR9W1U000883
285	KA9113	JMYLECR9W1U000992
286	KB2643	JMYLECR9W1U001031
287	KB3518	JMYLECR9W1U001025
288	KB4120	JMYLECR9W1U001018
289	KC3642	JMYLECR9W1U001046
290	KD3832	JMYLECR9W1U001048
291	KD6319	JMYLECR9W1U000902
292	KD6450	JMYLECR9W1U001037
293	KG630	JMYLECR9W1U000890
294	KG6637	JMYLECR9W1U001045
295	KH577	JMYLECR9W1U001078
296	KH6477	JMYLECR9W1U001073
297	KJ670	JMYLECR9W1U000869
298	KK3460	JMYLECR9W1U001092
299	KK5540	JMYLECR9W1U001065
300	KK6771	JMYLECR9W1U001086

# 車輛安全召回資訊

## Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: CR6W, CR9W

項目 Subject: 安裝儀錶電路板附加電線

Installation of combination meter circuit board sub harness

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	<b>Reg Mark</b>	<b>Chassis Number</b>
301	KK7897	JMYLECR9W1U001088
302	KK9489	JMYLECR9W1U000722
303	KL570	JMYLECR9W1U000838
304	KM3506	JMYLECR9W1U001142
305	KN6166	JMYLECR9W1U000466
306	KP1404	JMYLECR9W1U001149
307	KR1929	JMYLECR9W1U000884
308	KR8915	JMYLECR9W1U000812
309	KS2521	JMYLSCR6W2U000208
310	KS3520	JMYLECR5W2U000204
311	KS7374	JMYLSCR6W2U000210
312	KT6527	JMYLSCR6W2U000212
313	KT7161	JMYLSCR6W2U000202
314	KT8042	JMYLSCR6W2U000209
315	KT8440	JMYLSCR6W2U000205
316	KT8443	JMYLSCR6W2U000215
317	KU7347	JMYLECR5W2U000250
318	KV2877	JMYLSCR6W2U000228
319	KV7107	JMYLECR9W1U000461
320	LA5776	JMYLECR5W2U000254
321	LB3130	JMYLECR9W1U000655
322	LE7377	JMYLECR9W1U000670
323	LF4507	JMYLSCR6W2U000265
324	LN1631	JMYLECR9W1U000209
325	LT6968	JMYLECR9W1U000944