

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000280

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Outlander (CW5W), Delica D 5 (CV5W) & Lancer (CY0A)

項目 Subject: 更換迫力真空鼓單向閥

Replacement of check valve in brake booster

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Chassis Number	Model
1	JMYXLCW6W8Z000631	Outlander
2	JMYXLCW6W8Z000824	Outlander
3	JMYXLCW6W8Z000825	Outlander
4	JMYXLCW6W8Z000826	Outlander
5	JMYXLCW6W8Z000827	Outlander
6	JMYXLCW6W8Z000828	Outlander
7	JMYXLCW6W8Z000829	Outlander
8	JMYXLCW6W8Z000830	Outlander
9	JMYXLCW6W8Z000831	Outlander
10	JMYXLCW6W8Z000832	Outlander
11	JMYXLCW6W8Z000833	Outlander
12	JMYXLCW6W8Z000841	Outlander
13	JMYXLCW6W8Z000918	Outlander
14	JMYXLCW6W8Z000930	Outlander
15	JMYXLCW6W8Z001221	Outlander
16	JMYXLCW6W8Z001270	Outlander
17	JMYXLCW6W8Z001273	Outlander
18	JMYXLCW6W8Z001279	Outlander
19	JMYXLCW6W8Z001283	Outlander
20	JMYXLCW6W8Z001288	Outlander
21	JMYXTCW5W8Z001696	Outlander
22	JMYXTCW5W8Z001707	Outlander
23	JMYXTCW5W8Z001724	Outlander
24	JMYXTCW5W8Z001739	Outlander
25	JMYXTCW5W8Z001753	Outlander
26	JMYXTCW5W8Z001775	Outlander
27	JMYXTCW5W8Z001798	Outlander
28	JMYXTCW5W8Z001819	Outlander

	Chassis Number	Model
29	JMYXTCW5W8Z001838	Outlander
30	JMYXTCW5W8Z001856	Outlander
31	JMYXTCW5W8Z001868	Outlander
32	JMYXTCW5W8Z001899	Outlander
33	JMYXTCW5W8Z001911	Outlander
34	JMYXTCW5W8Z002029	Outlander
35	JMYXTCW5W8Z002041	Outlander
36	JMYXTCW5W8Z002068	Outlander
37	JMYXTCW5W8Z002072	Outlander
38	JMYXTCW5W8Z002202	Outlander
39	JMYXTCW5W8Z002219	Outlander
40	JMYXTCW5W8Z002276	Outlander
41	JMYXTCW5W8Z002295	Outlander
42	JMYXTCW5W8Z002305	Outlander
43	JMYXTCW5W8Z002307	Outlander
44	JMYXTCW5W8Z002308	Outlander
45	JMYXTCW5W8Z002323	Outlander
46	JMYXTCW5W8Z002331	Outlander
47	JMYXTCW5W8Z002339	Outlander
48	JMYXTCW5W8Z002344	Outlander
49	JMYXTCW5W8Z002346	Outlander
50	JMYXTCW5W8Z002347	Outlander
51	JMYLTCV5W7J000139	Delica D 5
52	JMYLTCV5W7J000141	Delica D 5
53	JMYLTCV5W7J000144	Delica D 5
54	JMYLTCV5W7J000145	Delica D 5
55	JMYLTCV5W7J000147	Delica D 5
56	JMYLTCV5W7J000148	Delica D 5

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000280

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Outlander (CW5W), Delica D 5 (CV5W) & Lancer (CY0A)

項目 Subject: 更換迫力真空鼓單向閥

Replacement of check valve in brake booster

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Chassis Number	Model
57	JMYLTCV5W7J000150	Delica D 5
58	JMYLTCV5W7J000153	Delica D 5
59	JMYLTCV5W7J000156	Delica D 5
60	JMYLTCV5W7J000159	Delica D 5
61	JMYLTCV5W7J000161	Delica D 5
62	JMYLTCV5W7J000162	Delica D 5
63	JMYLTCV5W7J000163	Delica D 5
64	JMYSTCY4A8U002342	Lancer
65	JMYSTCY4A8U002420	Lancer
66	JMYSTCY4A8U002423	Lancer
67	JMYSTCY4A8U002426	Lancer
68	JMYSTCY4A8U002427	Lancer
69	JMYSTCY4A8U002430	Lancer
70	JMYSTCY4A8U002431	Lancer
71	JMYSTCY4A8U002432	Lancer
72	JMYSTCY4A8U002436	Lancer
73	JMYSTCY4A8U002437	Lancer
74	JMYSTCY4A8U002442	Lancer
75	JMYSTCY4A8U002447	Lancer
76	JMYSTCY4A8U002449	Lancer
77	JMYSTCY4A8U002450	Lancer
78	JMYSTCY4A8U002455	Lancer
79	JMYSTCY4A8U002458	Lancer
80	JMYSTCY4A8U002464	Lancer
81	JMYSTCY4A8U002469	Lancer
82	JMYSTCY4A8U002474	Lancer
83	JMYSTCY4A8U002493	Lancer
84	JMYSTCY4A8U003117	Lancer

	Chassis Number	Model
85	JMYSTCY4A8U003121	Lancer
86	JMYSTCY4A8U003123	Lancer
87	JMYSTCY4A8U003127	Lancer
88	JMYSTCY4A8U003131	Lancer
89	JMYSTCY4A8U003134	Lancer
90	JMYSTCY4A8U003140	Lancer
91	JMYSTCY4A8U003142	Lancer
92	JMYSTCY4A8U003147	Lancer
93	JMYSTCY4A8U003149	Lancer
94	JMYSTCY4A8U003151	Lancer
95	JMYSTCY4A8U003154	Lancer
96	JMYSTCY4A8U003156	Lancer
97	JMYSTCY4A8U003160	Lancer
98	JMYSTCY4A8U003165	Lancer
99	JMYSTCY4A8U003168	Lancer
100	JMYSTCY4A8U003169	Lancer
101	JMYSTCY4A8U003170	Lancer
102	JMYSTCY4A8U003171	Lancer
103	JMYSTCY4A8U003393	Lancer
104	JMYSTCY4A8U003401	Lancer
105	JMYSTCY4A8U003417	Lancer
106	JMYSTCY4A8U003425	Lancer
107	JMYSTCY4A8U003432	Lancer
108	JMYSTCY4A8U003448	Lancer
109	JMYSTCY4A8U003451	Lancer
110	JMYSTCY4A8U003459	Lancer
111	JMYSTCY4A8U003473	Lancer
112	JMYSTCY4A8U003482	Lancer

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000280

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Outlander (CW5W), Delica D 5 (CV5W) & Lancer (CY0A)

項目 Subject: 更換迫力真空鼓單向閥

Replacement of check valve in brake booster

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Chassis Number	Model
113	JMYSTCY4A8U003490	Lancer
114	JMYSTCY4A8U003524	Lancer
115	JMYSTCY4A8U003532	Lancer
116	JMYSTCY4A8U003545	Lancer
117	JMYSTCY4A8U003551	Lancer
118	JMYSTCY4A8U003552	Lancer
119	JMYSTCY4A8U003560	Lancer
120	JMYSTCY4A8U003570	Lancer
121	JMYSTCY4A8U003592	Lancer
122	JMYSTCY4A8U003608	Lancer
123	JMYSTCY4A8U003612	Lancer
124	JMYSTCY4A8U003618	Lancer
125	JMYSTCY4A8U003627	Lancer
126	JMYSTCY4A8U003632	Lancer
127	JMYSTCY4A8U003637	Lancer
128	JMYSTCY4A8U003643	Lancer
129	JMYSTCY4A8U003646	Lancer
130	JMYSTCY4A8U003649	Lancer
131	JMYSTCY4A8U003658	Lancer
132	JMYSTCY4A8U003663	Lancer
133	JMYSTCY4A8U003669	Lancer
134	JMYSTCY4A8U003671	Lancer
135	JMYSTCY4A8U003676	Lancer
136	JMYSTCY4A8U003679	Lancer
137	JMYSTCY4A8U003684	Lancer
138	JMYSTCY4A8U003691	Lancer
139	JMYSTCY4A8U003694	Lancer
140	JMYSTCY4A8U003695	Lancer

	Chassis Number	Model
141	JMYSTCY4A8U003699	Lancer
142	JMYSTCY4A8U003709	Lancer
143	JMYSTCY4A8U003712	Lancer
144	JMYSTCY4A8U003718	Lancer
145	JMYSTCY4A8U003722	Lancer
146	JMYSTCY4A8U003723	Lancer
147	JMYSTCY4A8U003727	Lancer
148	JMYSTCY4A8U003728	Lancer
149	JMYSTCY4A8U003730	Lancer
150	JMYSTCY4A9U001706	Lancer
151	JMYSTCY4A9U001725	Lancer
152	JMYSTCY4A9U001746	Lancer
153	JMYSTCY4A9U001750	Lancer
154	JMYSTCY4A9U001763	Lancer