

車輛安全召回資訊

Vehicle Safety Recall Information

10000306

製造商 Make: 鈴木汽車 Suzuki Motor Corporation

型號 Model: Every GE306

項目 Subject: 防結冰裝置失效安全召回

Safety Recall Campaign For Inoperative Defroster

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1	DA64V131140
2	DA64V131479
3	DA64V139405
4	DA64V139465
5	DA64V139519
6	DA64V140592
7	DA64V141531
8	DA64V143919
9	DA64V145973
10	DA64V146513
11	DA64V147042
12	DA64V150127
13	DA64V150255
14	DA64V154040
15	DA64V154956
16	DA64V155445
17	DA64V155729
18	DA64V156294
19	DA64V160489
20	DA64V160738
21	DA64V161237
22	DA64V161582
23	DA64V161854
24	DA64V161863
25	DA64V164152
26	DA64V164631
27	DA64V165096
28	DA64V165501
29	DA64V165909
30	DA64V166147
31	DA64V166800
32	DA64V166967
33	DA64V167807
34	DA64V168844

35	DA64V168847
36	DA64V169419
37	DA64V170019
38	DA64V170227
39	DA64V170475
40	DA64V171249
41	DA64V171838
42	DA64V172283
43	DA64V172996
44	DA64V177765
45	DA64V179781
46	DA64V180098
47	DA64V181046
48	DA64V181293
49	DA64V181603
50	DA64V186318
51	DA64V186427
52	DA64V189750
53	DA64V189918
54	DA64V190717
55	DA64V191366
56	DA64V191873
57	DA64V192052
58	DA64V193975
59	DA64V194317
60	DA64V196730
61	DA64V197260
62	DA64V198600
63	DA64V198725
64	DA64V199183
65	DA64V199491
66	DA64V200210
67	DA64V200587
68	DA64V201481

車輛安全召回資訊

Vehicle Safety Recall Information

10000306

製造商 Make: 鈴木汽車 Suzuki Motor Corporation

型號 Model: Every GE306

項目 Subject: 防結冰裝置失效安全召回

Safety Recall Campaign For Inoperative Defroster

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

69	DA64V202513	103	DA64V276112
70	DA64V203152	104	DA64V279111
71	DA64V204997	105	DA64V279649
72	DA64V205555	106	DA64V291363
73	DA64V214227	107	DA64V291597
74	DA64V246354	108	DA64V291852
75	DA64V249785	109	DA64V292803
76	DA64V250079	110	DA64V293249
77	DA64V250446	111	DA64V293943
78	DA64V252526	112	DA64V294882
79	DA64V253113	113	DA64V295515
80	DA64V253344	114	DA64V295707
81	DA64V253712	115	DA64V295932
82	DA64V254168	116	DA64V298014
83	DA64V254326	117	DA64V301512
84	DA64V254506	118	DA64V301674
85	DA64V254839	119	DA64V302618
86	DA64V255003	120	DA64V303326
87	DA64V257780	121	DA64V311819
88	DA64V257873	122	DA64V312073
89	DA64V258234	123	DA64V312193
90	DA64V258491	124	DA64V312339
91	DA64V258998	125	DA64V312463
92	DA64V259126	126	DA64V312578
93	DA64V260006	127	DA64V312695
94	DA64V261343	128	DA64V312820
95	DA64V261999	129	DA64V312935
96	DA64V262581	130	DA64V313174
97	DA64V263184	131	DA64V313273
98	DA64V263758	132	DA64V313357
99	DA64V264022	133	DA64V313507
100	DA64V264680	134	DA64V313769
101	DA64V265342	135	DA64V313903
102	DA64V275324	136	DA64V314283

車輛安全召回資訊

Vehicle Safety Recall Information

10000306

製造商 Make: 鈴木汽車 Suzuki Motor Corporation

型號 Model: Every GE306

項目 Subject: 防結冰裝置失效安全召回

Safety Recall Campaign For Inoperative Defroster

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

137	DA64V314816
138	DA64V315315
139	DA64V315697
140	DA64V327448
141	DA64V328029
142	DA64V330052
143	DA64V330592
144	DA64V331378
145	DA64V365660
146	DA64V365889

147	DA64V371176
148	DA64V371178
149	DA64V371567
150	DA64V371651
151	DA64V372161
152	DA64V374649
153	DA64V375094
154	DA64V375454
155	DA64V376173