

Recall Detail	
Ref No	10000416
Manufacturer	Mitsubishi Motors Corporation
Vehicle Class	Light Goods Vehicle
Model/Type	MINICAB-MiEV (U67V)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Brake Vacuum Assist System
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	In the vacuum pump of the brake system, the vane with the cracks caused by inappropriate manufacturing process may have been incorporated into the production. If use continues under this condition, the vane in the vacuum pump would be broken causing the vacuum pump to be inoperable which could result in increasing the stopping distance.
Remedial Action	Replacement of brake vacuum pump.
Build Dates	2012
Launch Date	28/01/2013
Tentative Date of Recall Completion	27/01/2014