Recall Detail	
Ref No	10000597
Manufacturer	Daimler AG
Vehicle Class	Heavy Goods Vehicle
Model/Type	Actros, Antos, Arocs / 936, 964
Dealer (phone no)	Zung Fu Commercial Vehicle Service Centre: 2637 2988
Subject	Replace seal on exhaust tailpipe of option code K7D, K7C and K7N (4992555)
Progress	Completed
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centre at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall
	Vehicles with exhaust tailpipe variants K7D, K7C and K7N, erosion of the seal on the exhaust tailpipe flange may occur as a result of the combination of water with salt.
Description of Defect, how it came to light, and possible consequences if ignored.	It is possible that if the seal is only partially present or is no longer present, the threaded connection is no longer under tension and the 3 mounting screws will work loose and unscrew due to vibrations. With tailpipe variant K7D, the exhaust tailpipe may fall onto the road if the threaded connection is lost. This could constitute a risk of accident. In the event that the threaded connection is lost, it also cannot be ruled out that the exhaust stream, which is no longer guided, causes thermal damage to adjacent components and therefore constitutes a risk of fire.
Remedial Action	As a precaution, replace the seal on the exhaust tailpipe flange on the affected vehicles with a metal bead gasket.
<b>Build Dates</b>	14/05/2014 - 12/03/2016
Launch Date	17/6/2016
Tentative Date of	31/12/2016

## **Recall Completion**