

表 4.5 : 驗車中心車輛檢驗數字 (二零一八年二月)
Table 4.5 : Vehicle Inspections at Vehicle Examination Centres (February 2018)

2018/02

		政府運作的驗車中心 Vehicle Inspections at Government Operated Vehicle Examination Centres																								總計 Total		
		電單車 ⁽¹⁾ Motor Cycles ⁽¹⁾	私家車 ⁽¹⁾ Private Cars ⁽¹⁾	的士 Taxis					巴士 Buses								小巴 Light Buses			貨車 ⁽²⁾ Goods Vehicles ⁽²⁾				拖車 Trailers				
				新界及大嶼山 NT & Lantau	市區 Urban	收費錶 檢查 Meter Check	新車 New	專營 Franchised				其他 Others				年檢 Annual		新車 New	年檢 Annual		首次登記 First Registration	年檢 Annual	首次登記 First Registration	其他 Others				
								九巴 KMB	城巴 City- bus	新巴 NWFB	龍運 LWB	新大嶼山 巴士 NLB	首次登記 First Registration	港鐵 巴士 MTR Buses	公共 Public	私家 Private	首次登記 First Registration		公共 Public	私家 Private					≤16 公噸 ≤16 Tonnes		>16 公噸 >16 Tonnes	
A. 為發牌及續牌而進行的車輛檢驗 Vehicle Inspection for Licensing & Re-licensing																												
驗車數字 No. of Vehicle Inspections		111	980	141	906	1 708	80	207	67	48	12	6	31	7	428	40	34	248	143	54	14	741	365	2	13	25	6 411	
首次檢驗 First Inspection	及格 Passed	COR	108	891	133	865	1 688	80	207	67	48	12	2	-	7	371	38	31	230	134	54	8	654	336	1	13	18	5 996
	不及格 Failed	COF	-	-	-	-	-	-	-	-	-	-	2	31	-	5	-	-	-	-	-	-	-	-	-	-	-	38
其他檢驗 Other Inspection	覆驗 Re-checks	Failed	2	50	4	19	12	-	-	-	-	-	1	-	-	21	1	1	9	4	-	3	42	14	1	-	4	188
	車架檢驗 Frame Checks	Re-checks	1	39	4	22	8	-	-	-	-	-	1	-	-	26	1	2	9	5	-	3	45	15	-	-	3	184
不送檢 Did not Attend	Frame Checks	Failed	-	-	-	-	-	-	-	-	-	-	-	-	-	5	-	-	-	-	-	-	-	-	-	-	-	5
不送檢 Did not Attend	Frame Checks	Failed	-	27	2	15	124	-	-	-	-	-	-	-	-	17	2	-	-	3	1	2	20	2	2	-	1	218
預約數字 No. of Appointments	Frame Checks	Failed	111	1 007	143	921	1 832	80	207	67	48	12	6	31	7	445	42	34	248	146	55	16	761	367	4	13	26	6 629
暫停牌照 Suspension Orders	Frame Checks	Failed	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3	-	-	-	-	3
B. 其他檢驗 Other Inspection																												
驗車數字 No. of Vehicle Inspections		29	393	3	111	-	-	65	65	37	2	3	-	2	39	3	-	43	5	-	104	44	-	-	-	-	3	951
VIO 檢驗 VIO Inspection	及格 Passed	Failed	12	225	2	80	-	-	-	-	-	-	-	-	1	-	-	32	5	-	60	37	-	-	-	-	2	456
	不及格 Failed	Failed	1	41	-	3	-	-	-	-	-	-	-	-	-	-	-	1	-	-	2	-	-	-	-	-	-	48
突擊檢驗 Spot Checks	不及格 Failed	Failed	2	93	1	11	-	-	-	-	-	-	-	-	1	-	-	7	2	-	29	10	-	-	-	-	1	157
	不送檢 Did not Attend	Failed	-	-	-	-	-	-	61	65	33	2	2	-	2	34	3	-	-	-	-	-	-	-	-	-	-	202
警方對涉及意外車輛的檢驗 Police Accident Inspection	Failed	Failed	10	56	-	12	-	-	4	-	4	-	1	-	-	3	-	3	-	-	12	6	-	-	-	-	1	112
警方為執法和控制交通而進行的檢驗 Police Enforcement and Control Inspection	Failed	Failed	6	71	1	16	-	-	-	-	-	-	-	-	1	-	-	7	-	-	30	1	-	-	-	-	-	133
預約總數 Total Appointments	Failed	Failed	31	486	4	122	-	-	65	65	37	2	3	-	2	40	3	-	50	7	-	133	54	-	-	-	4	1 108
暫停牌照 Suspension Orders	Failed	Failed	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	2	-	-	-	-	-	2

註：(1) 車輛檢驗只包括登記前、重行登記及特定的檢驗。

Note : (1) Vehicle inspections include pre-registration, re-registration and miscellaneous inspections only.

COR - 檢驗汽車機械及格證書
COF - 機動車輛全面檢驗及格證書
VIO - 車輛檢驗事務處

COR - Certificate of Road-worthiness
COF - Certificate of Fitness
VIO - Vehicle Inspection Office

表 4.5 (續)

Table 4.5 (cont'd)

2018/02

		其他驗車中心為續牌而進行的車輛檢驗					
		Vehicle Inspections at Other Examination Centres for Re-licensing					
		私家車 Private Cars	輕型貨車 Light Goods Vehicles		中型貨車 Medium Goods Vehicles		拖車 Trailers
少於1.9公噸 <1.9 Tonnes	1.9至5.5公噸 1.9 - 5.5 Tonnes		> 5.5至16公噸 > 5.5 - 16 Tonnes				
A. 新九龍灣驗車中心 New Kowloon Bay Vehicle Examination Centre							
驗車數字 No. of Vehicle Inspections		-	-	3 394	1 704	639	5 737
首次檢驗 First Inspection	及格 Passed	-	-	3 188	1 554	594	5 336
	不及格 Failed	-	-	101	73	22	196
其他檢驗 Other Inspection	覆驗 Re-checks	-	-	105	77	23	205
不送檢 Did not Attend		-	-	44	48	24	116
預約數字 No. of Appointments		-	-	3 438	1 752	663	5 853
暫停牌照 Suspension Orders		-	-	-	-	-	-
B. 指定車輛驗車中心 Designated Car Testing Centre							
驗車數字 No. of Vehicle Inspections		18 885	2	-	-	-	18 887
首次檢驗 First Inspection	及格 Passed	16 858	2	-	-	-	16 860
	不及格 Failed	1 072	-	-	-	-	1 072
其他檢驗 Other Inspection	覆驗 Re-checks	955	-	-	-	-	955
不送檢 Did not Attend		-	-	-	-	-	-
預約數字 No. of Appointments		18 885	2	-	-	-	18 887
暫停牌照 Suspension Orders		-	-	-	-	-	-

資料來源：車輛安全及標準部

Source : Vehicle Safety and Standards Division