

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

08 MY F-Series	
1	JALFRR34L87000037
2	JALFRR34L87000038
3	JALFRR34L87000157
4	JALFRR34L87000158
5	JALFRR34L87000161
6	JALFRR34L87000162
7	JALFRR34L87000164
8	JALFRR34L87000169
9	JALFRR34L87000174
10	JALFRR34L87000201
11	JALFRR34L87000203
12	JALFRR34L97000001
13	JALFRR34L97000002
14	JALFRR34L97000006
15	JALFRR34N87000001
16	JALFRR34N87000002
17	JALFRR34N87000003
18	JALFRR34N87000004
19	JALFRR34N87000007
20	JALFRR34N87000008
21	JALFRR34N87000009
22	JALFRR34N87000010
23	JALFRR34N87000011
24	JALFRR34N87000012
25	JALFRR34N87000013
26	JALFRR34N87000014
27	JALFRR34N87000015
28	JALFRR34N87000016
29	JALFRR34N87000017
30	JALFRR34N87000018
31	JALFSR34N87000001
32	JALFSR34N87000002
33	JALFSR34N87000003
34	JALFSR34N87000004
35	JALFSR34N87000005
36	JALFSR34N87000006
37	JALFSR34N87000012
38	JALFSR34N87000013
39	JALFSR34N87000014
40	JALFSR34N87000015
41	JALFSR34N87000016
42	JALFSR34N87000017
43	JALFSR34N87000018
44	JALFSR34N87000019
45	JALFSR34N87000020
46	JALFSR34N87000021
47	JALFSR34N87000022
48	JALFSR34N87000023
49	JALFTR34787000016
50	JALFTR34787000017
51	JALFTR34787000018
52	JALFTR34787000031
53	JALFTR34797000025
54	JALFTR34797000038
55	JALFTR34797000039
56	JALFTR34P87000017
57	JALFTR34P87000018
58	JALFTR34P87000050
59	JALFTR34P87000051
60	JALFTR34P87000052
61	JALFTR34P87000053
62	JALFTR34P97000019
63	JALFTR34P97000026
64	JALFTR34P97000027
65	JALFTR34P97000028
66	JALFVR34787000018
67	JALFVR34787000019

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

68	JALFVR34787000020	103	JALFVR34787000086
69	JALFVR34787000021	104	JALFVR34787000088
70	JALFVR34787000023	105	JALFVR34787000089
71	JALFVR34787000024	106	JALFVR34787000090
72	JALFVR34787000025	107	JALFVR34787000091
73	JALFVR34787000026	108	JALFVR34787000094
74	JALFVR34787000027	109	JALFVR34787000095
75	JALFVR34787000028	110	JALFVR34787000096
76	JALFVR34787000029	111	JALFVR34787000106
77	JALFVR34787000030	112	JALFVR34787000107
78	JALFVR34787000032	113	JALFVR34787000108
79	JALFVR34787000033	114	JALFVR34787000111
80	JALFVR34787000035	115	JALFVR34787000112
81	JALFVR34787000037	116	JALFVR34787000113
82	JALFVR34787000038	117	JALFVR34787000114
83	JALFVR34787000039	118	JALFVR34787000115
84	JALFVR34787000049	119	JALFVR34787000116
85	JALFVR34787000051	120	JALFVR34787000117
86	JALFVR34787000053	121	JALFVR34787000120
87	JALFVR34787000055	122	JALFVR34787000123
88	JALFVR34787000057	123	JALFVR34787000127
89	JALFVR34787000059	124	JALFVR34787000129
90	JALFVR34787000061	125	JALFVR34787000130
91	JALFVR34787000062	126	JALFVR34787000132
92	JALFVR34787000064	127	JALFVR34787000134
93	JALFVR34787000065	128	JALFVR34787000136
94	JALFVR34787000067	129	JALFVR34787000137
95	JALFVR34787000068	130	JALFVR34787000139
96	JALFVR34787000069	131	JALFVR34787000141
97	JALFVR34787000071	132	JALFVR34787000143
98	JALFVR34787000073	133	JALFVR34787000146
99	JALFVR34787000075	134	JALFVR34787000148
100	JALFVR34787000078	135	JALFVR34787000149
101	JALFVR34787000082	136	JALFVR34787000159
102	JALFVR34787000083	137	JALFVR34787000161

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

138	JALFVR34787000162
139	JALFVR34787000165
140	JALFVR34787000168
141	JALFVR34787000170
142	JALFVR34787000173
143	JALFVR34787000175
144	JALFVR34787000178
145	JALFVR34787000179
146	JALFVR34M87000043
147	JALFVR34M87000050
148	JALFVR34M87000051
149	JALFVR34M87000052
150	JALFVR34M87000053
151	JALFVR34M87000054
152	JALFVR34M87000055
153	JALFVR34M87000086
154	JALFVR34M87000087
155	JALFVR34M87000088
156	JALFVR34M87000089
157	JALFVR34S87000001
158	JALFVR34S87000002
159	JALFVR34S87000003
160	JALFVR34S87000004
161	JALFVR34S87000005
162	JALFVR34S87000006
163	JALFVR34S87000007
164	JALFVR34S87000008
165	JALFVR34S87000009
166	JALFVR34S87000010
167	JALFVR34S87000011
168	JALFVR34S87000012
169	JALFVR34S87000013
170	JALFVR34S87000014
171	JALFVR34S87000015
172	JALFVR34S87000016

173	JALFVR34S87000017
174	JALFVR34S87000018
175	JALFVR34S87000019
176	JALFVR34S87000020
177	JALFVR34S87000021
178	JALFVR34S87000022
179	JALFVR34S87000023
180	JALFVR34S87000024
181	JALFVR34S87000025
182	JALFVR34S87000026
183	JALFVR34S87000027
184	JALFVR34S87000028
185	JALFVR34S87000029
186	JALFVR34S87000030
187	JALFVR34S87000031
188	JALFVR34S87000032
189	JALFVR34S87000033
190	JALFVR34S87000034
191	JALFVR34S87000035
192	JALFVR34S87000036
193	JALFVR34S87000040
194	JALFVR34S87000041
195	JALFVR34S87000042
196	JALFVR34S87000043
197	JALFVR34S87000044
198	JALFVR34S87000045
199	JALFVR34S87000046
200	JALFVR34S87000047
201	JALFVR34S87000048
202	JALFVR34S87000049
203	JALFVR34S87000050
204	JALFVR34S87000051
205	JALFVR34S87000052
206	JALFVR34S87000053
207	JALFVR34S87000054

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

208	JALFVR34S87000055
209	JALFVR34S87000056
210	JALFVR34S87000057
211	JALFVR34S87000058
212	JALFVR34S87000059
213	JALFVR34S87000060
214	JALFVR34S87000061
215	JALFVR34S87000062
216	JALFVR34S87000063
217	JALFVR34S87000064
218	JALFVR34S87000065
219	JALFVR34S87000066
220	JALFVR34S87000067
221	JALFVR34S87000068
222	JALFVR34S87000069
223	JALFVR34S87000070
224	JALFVR34S87000071
225	JALFVR34S87000072
226	JALFVR34S87000073
227	JALFVR34S87000074
228	JALFVR34S87000075
229	JALFVR34S87000076
230	JALFVR34S87000077
231	JALFVR34S87000078
232	JALFVR34S87000079
233	JALFVR34S87000080
234	JALFVR34S87000081
235	JALFVR34S87000082
236	JALFVR34S87000083
237	JALFVR34S87000084
238	JALFVR34S87000085
239	JALFVR34S87000086
240	JALFVR34S87000087
241	JALFVR34S87000088
242	JALFVR34S87000089

243	JALFVR34S87000090
244	JALFVR34S87000091
245	JALFVR34S87000092
246	JALFVR34S87000093
247	JALFVR34S87000094
248	JALFVR34S87000095
249	JALFVR34S87000096
250	JALFVR34S87000097
251	JALFVR34S87000098
252	JALFVR34S87000099
253	JALFVR34S87000100
254	JALFVR34S87000101
255	JALFVR34S87000102
256	JALFVR34S87000103
257	JALFVR34S87000104
258	JALFVR34S87000105
259	JALFVR34S87000106
260	JALFVR34S87000107
261	JALFVR34S87000108
262	JALFVR34S87000109
263	JALFVR34S87000110
264	JALFVR34S87000111
265	JALFVR34S87000112
266	JALFVR34S87000113
267	JALFVR34S87000114
268	JALFVR34S87000115
269	JALFVR34S87000116
270	JALFVR34S87000117
271	JALFVR34S87000118
272	JALFVR34S87000119
273	JALFVR34S87000120
274	JALFVR34S87000121
275	JALFVR34S87000122
276	JALFVR34S87000123
277	JALFVR34S87000124

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

278	JALFVR34S87000125
279	JALFVR34S87000126
280	JALFVR34S87000127
281	JALFVR34S87000128
282	JALFVR34S87000129
283	JALFVR34S87000130
284	JALFVR34S87000131
285	JALFVR34S87000132
286	JALFVR34S87000133
287	JALFVR34S87000134
288	JALFVR34S87000135
289	JALFVR34S87000136
290	JALFVR34S87000137
291	JALFVR34S87000138
292	JALFVR34S87000139
293	JALFVR34S87000140
294	JALFVR34S87000141
295	JALFVR34S87000142
296	JALFVR34S87000143
297	JALFVR34S87000144
298	JALFVR34S87000145
299	JALFVR34S87000146
300	JALFVR34S87000147
301	JALFVR34S87000148
302	JALFVR34S87000149
303	JALFVR34S87000150
304	JALFVR34S87000151
305	JALFVR34S87000152
306	JALFVR34S87000153
307	JALFVR34S87000154
308	JALFVR34S87000155
309	JALFVR34S87000156
310	JALFVR34S87000157
311	JALFVR34S87000158
312	JALFVR34S87000159

313	JALFVR34S87000160
314	JALFVR34S87000161
315	JALFVR34S87000162
316	JALFVR34S87000163
317	JALFVR34S87000164
318	JALFVR34S87000165
319	JALFVR34S87000166
320	JALFVR34S87000167
321	JALFVR34S87000168
322	JALFVR34S87000169
323	JALFVR34S87000170
324	JALFVR34S87000171
325	JALFVR34S87000172
326	JALFVR34S87000173
327	JALFVR34S87000174
328	JALFVR34S87000175
329	JALFVR34S87000176
330	JALFVR34S87000177
331	JALFVR34S87000178
332	JALFVR34S87000179
333	JALFVR34S87000180

07-08 MY N-Series

334	JAAN1R75K87100004
335	JAAN1R75K87100005
336	JAAN1R75K87100006
337	JAAN1R75K87100007
338	JAAN1R75K87100009
339	JAAN1R75K87100010
340	JAAN1R75K87100011
341	JAAN1R75K87100012
342	JAAN1R75K87100013
343	JAAN1R75K87100014
344	JAAN1R75K87100015
345	JAAN1R75K87100016
346	JAAN1R75K87100017

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

347	JAAN1R75K87100018
348	JAAN1R75K87100019
349	JAAN1R75K87100021
350	JAAN1R75K87100025
351	JAAN1R75K87100027
352	JAAN1R75K87100028
353	JAAN1R75K87100029
354	JAAN1R75K87100030
355	JAAN1R75K87100031
356	JAAN1R75K87100032
357	JAAN1R75K87100033
358	JAAN1R75K87100034
359	JAAN1R75K87100035
360	JAAN1R75K87100036
361	JAAN1R75K87100037
362	JAAN1R75K87100038
363	JAAN1R75K87100039
364	JAAN1R75K87100040
365	JAAN1R75K87100041
366	JAAN1R75K87100043
367	JAAN1R75K87100044
368	JAAN1R75K87100045
369	JAAN1R75K87100046
370	JAAN1R75K87100047
371	JAAN1R75K87100048
372	JAAN1R75K87100049
373	JAAN1R75K87100050
374	JAAN1R75K87100051
375	JAAN1R75K87100053
376	JAAN1R75K87100055
377	JAAN1R75K87100056
378	JAAN1R75K87100057
379	JAAN1R75K87100058
380	JAAN1R75K87100059
381	JAAN1R75K87100060

382	JAAN1R75K87100061
383	JAAN1R75K87100062
384	JAAN1R75K87100063
385	JAAN1R75K87100064
386	JAAN1R75K87100065
387	JAAN1R75K87100066
388	JAAN1R75K87100067
389	JAAN1R75K87100068
390	JAAN1R75K87100069
391	JAAN1R75K87100070
392	JAAN1R75K87100071
393	JAAN1R75K87100072
394	JAAN1R75K87100074
395	JAAN1R75K87100075
396	JAAN1R75K87100076
397	JAAN1R75K87100077
398	JAAN1R75K87100078
399	JAAN1R75K87100079
400	JAAN1R75K87100080
401	JAAN1R75K87100081
402	JAAN1R75K87100082
403	JAAN1R75K87100083
404	JAAN1R75K87100085
405	JAAN1R75K87100086
406	JAAN1R75K87100087
407	JAAN1R75K87100090
408	JAAN1R75K87100091
409	JAAN1R75K87100092
410	JAAN1R75K87100093
411	JAAN1R75K87100094
412	JAAN1R75K87100095
413	JAAN1R75K87100096
414	JAAN1R75K87100097
415	JAAN1R75K87100098
416	JAAN1R75K87100099

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

417	JAAN1R75K87100100
418	JAAN1R75K87100101
419	JAAN1R75K87100102
420	JAAN1R75K87100103
421	JAAN1R75K87100104
422	JAAN1R75K87100105
423	JAAN1R75K87100106
424	JAAN1R75K87100107
425	JAAN1R75K87100108
426	JAAN1R75K87100109
427	JAAN1R75K87100110
428	JAAN1R75K87100111
429	JAAN1R75K87100112
430	JAAN1R75K87100113
431	JAAN1R75K87100114
432	JAAN1R75K87100115
433	JAAN1R75K87100116
434	JAAN1R75K87100119
435	JAAN1R75K87100120
436	JAAN1R75K87100121
437	JAAN1R75K87100122
438	JAAN1R75K87100123
439	JAAN1R75K87100124
440	JAAN1R75K87100125
441	JAAN1R75K87100126
442	JAAN1R75K87100127
443	JAAN1R75K87100128
444	JAAN1R75K87100129
445	JAAN1R75K87100130
446	JAAN1R75K87100131
447	JAAN1R75K87100132
448	JAAN1R75K87100133
449	JAAN1R75K87100134
450	JAAN1R75K87100135
451	JAAN1R75K87100136

452	JAAN1R75K87100137
453	JAAN1R75K87100138
454	JAAN1R75K87100139
455	JAAN1R75K87100140
456	JAAN1R75K87100141
457	JAAN1R75K87100142
458	JAAN1R75K87100143
459	JAAN1R75K87100145
460	JAAN1R75K87100146
461	JAAN1R75K87100147
462	JAAN1R75K87100148
463	JAAN1R75K87100149
464	JAAN1R75K87100150
465	JAAN1R75K87100151
466	JAAN1R75K87100152
467	JAAN1R75K87100153
468	JAAN1R75K87100154
469	JAAN1R75K87100155
470	JAAN1R75K87100156
471	JAAN1R75K87100158
472	JAAN1R75K87100159
473	JAAN1R75K87100160
474	JAAN1R75K87100161
475	JAAN1R75K87100162
476	JAAN1R75K87100163
477	JAAN1R75K87100164
478	JAAN1R75K87100165
479	JAAN1R75K87100166
480	JAAN1R75K87100167
481	JAAN1R75K87100168
482	JAAN1R75K87100169
483	JAAN1R75K87100170
484	JAAN1R75K87100171
485	JAAN1R75K87100172
486	JAAN1R75K87100173

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

487	JAAN1R75K87100174
488	JAAN1R75K87100175
489	JAAN1R75K87100176
490	JAAN1R75K87100177
491	JAAN1R75K87100178
492	JAAN1R75K87100179
493	JAAN1R75K87100180
494	JAAN1R75K87100182
495	JAAN1R75K87100183
496	JAAN1R75K87100184
497	JAAN1R75K87100185
498	JAAN1R75K87100186
499	JAAN1R75K87100187
500	JAAN1R75K87100188
501	JAAN1R75K87100189
502	JAAN1R75K87100190
503	JAAN1R75K87100191
504	JAAN1R75K87100192
505	JAAN1R75K87100193
506	JAAN1R75K87100194
507	JAAN1R75K87100195
508	JAAN1R75K87100196
509	JAAN1R75K87100197
510	JAAN1R75K87100198
511	JAAN1R75K87100199
512	JAAN1R75K87100200
513	JAAN1R75K87100202
514	JAAN1R75K87100204
515	JAAN1R75K87100205
516	JAAN1R75K87100206
517	JAAN1R75K87100207
518	JAAN1R75K87100208
519	JAAN1R75K87100210
520	JAAN1R75K87100211
521	JAAN1R75K87100213

522	JAAN1R75K87100214
523	JAAN1R75K87100215
524	JAAN1R75K87100216
525	JAAN1R75K87100221
526	JAAN1R75K87100222
527	JAAN1R75K87100223
528	JAAN1R75K87100224
529	JAAN1R75K87100225
530	JAAN1R75K87100226
531	JAAN1R75K87100227
532	JAAN1R75K87100228
533	JAAN1R75K87100229
534	JAAN1R75K87100230
535	JAAN1R75K87100231
536	JAAN1R75K87100232
537	JAAN1R75K87100233
538	JAAN1R75K87100234
539	JAAN1R75K87100235
540	JAAN1R75K87100236
541	JAAN1R75K87100237
542	JAAN1R75K87100238
543	JAAN1R75K87100239
544	JAAN1R75K87100240
545	JAAN1R75K97100013
546	JAAN1R75K97100014
547	JAAN1R75K97100015
548	JAAN1R75K97100016
549	JAAN1R75K97100017
550	JAAN1R75K97100018
551	JAAN1R75K97100019
552	JAAN1R75K97100020
553	JAAN1R75K97100021
554	JAAN1R75K97100022
555	JAAN1R75K97100023
556	JAAN1R75K97100024

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

557	JAAN1R75K97100025
558	JAAN1R75K97100026
559	JAAN1R75K97100027
560	JAAN1R75K97100034
561	JAAN1R75K97100035
562	JAAN1R75K97100036
563	JAAN1R75K97100037
564	JAAN1R75K97100038
565	JAAN1R75K97100039
566	JAAN1R75K97100040
567	JAAN1R75K97100041
568	JAAN1R75K97100042
569	JAAN1R75K97100043
570	JAAN1R75K97100047
571	JAAN1R75K97100051
572	JAAN1R75K97100052
573	JAAN1R75K97100053
574	JAAN1R75K97100054
575	JAAN1R75K97100056
576	JAAN1R75K97100059
577	JAAN1R75K97100060
578	JAAN1R75L87100047
579	JAAN1R75L87100048
580	JAAN1R75L87100049
581	JAAN1R75L87100050
582	JAAN1R75L87100051
583	JAAN1R75L87100052
584	JAAN1R75L87100053
585	JAAN1R75L87100054
586	JAAN1R75L87100055
587	JAAN1R75L87100056
588	JAAN1R75L87100057
589	JAAN1R75L87100092
590	JAAN1R75L87100093
591	JAAN1R75L87100094

592	JAAN1R75L87100389
593	JAAN1R75L87100390
594	JAAN1R75L87100598
595	JAAN1R75L87100599
596	JAAN1R75L87100600
597	JAAN1R75L87100601
598	JAAN1R75L87100602
599	JAAN1R75L87100657
600	JAAN1R75L87100658
601	JAAN1R75L87100659
602	JAAN1R75L87100660
603	JAAN1R75L87100661
604	JAAN1R75L87100662
605	JAAN1R75L87100663
606	JAAN1R75L87100678
607	JAAN1R75L87100679
608	JAAN1R75L87100680
609	JAAN1R75L87100699
610	JAAN1R75L87100700
611	JAAN1R75L87100701
612	JAAN1R75L87100702
613	JAAN1R75L87100703
614	JAAN1R75L87100704
615	JAAN1R75L87100705
616	JAAN1R75L87100718
617	JAAN1R75L87100719
618	JAAN1R75L87100726
619	JAAN1R75L87100824
620	JAAN1R75L87100825
621	JAAN1R75L87100826
622	JAAN1R75L87100827
623	JAAN1R75L87100828
624	JAAN1R75L97100335
625	JAAN1R75L97100336
626	JAAN1R75L97100337

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

627	JAAN1R75L97100338
628	JAAN1R75L97100339
629	JAAN1R75L97100423
630	JAAN1R75L97100424
631	JAAN1R75L97100425
632	JAAN1R75L97100426
633	JAAN1R75L97100427
634	JAAN1R75L97100501
635	JAAN1R75L97100502
636	JAAN1R75L97100503
637	JAAN1R75L97100705
638	JAAN1R75L97100742
639	JAAN1R75L97100743
640	JAAN1R75L97100744
641	JAAN1R75P77100148
642	JAAN1R75P77101014
643	JAAN1R75P77101075
644	JAANMR85E87100003
645	JAANMR85E87100017
646	JAANMR85E87100018
647	JAANMR85E87100019
648	JAANMR85E87100020
649	JAANMR85E87100082
650	JAANMR85E87100155
651	JAANMR85E87100156
652	JAANMR85E87100193
653	JAANMR85E87100194
654	JAANMR85E87100195
655	JAANMR85E87100220
656	JAANMR85E87100221
657	JAANMR85E87100246
658	JAANMR85E87100259
659	JAANMR85E87100260
660	JAANMR85E87100267
661	JAANMR85E87100268

662	JAANMR85E87100275
663	JAANMR85E97100124
664	JAANMR85E97100125
665	JAANMR85E97100126
666	JAANMR85E97100343
667	JAANMR85E97100344
668	JAANMR85E97100345
669	JAANMR85H87100010
670	JAANMR85H87100011
671	JAANMR85H87100012
672	JAANMR85H87100141
673	JAANMR85H87100238
674	JAANMR85H87100239
675	JAANPR75F87100073
676	JAANPR75F87100074
677	JAANPR75F87100076
678	JAANPR75F87100079
679	JAANPR75F87100097
680	JAANPR75F87100105
681	JAANPR75F87100107
682	JAANPR75F87100152
683	JAANPR75F87100153
684	JAANPR75F87100154
685	JAANPR75F87100155
686	JAANPR75F87100178
687	JAANPR75F87100179
688	JAANPR75F87100180
689	JAANPR75F87100184
690	JAANPR75F87100185
691	JAANPR75F87100187
692	JAANPR75F87100188
693	JAANPR75F87100189
694	JAANPR75F87100218
695	JAANPR75F87100219
696	JAANPR75F87100220

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

697	JAANPR75F87100221
698	JAANPR75F87100222
699	JAANPR75F87100223
700	JAANPR75F87100241
701	JAANPR75F87100243
702	JAANPR75F87100245
703	JAANPR75F87100251
704	JAANPR75F87100252
705	JAANPR75F87100253
706	JAANPR75F87100258
707	JAANPR75F87100260
708	JAANPR75F87100261
709	JAANPR75F87100263
710	JAANPR75F87100265
711	JAANPR75F87100268
712	JAANPR75F97100009
713	JAANPR75F97100010
714	JAANPR75F97100011
715	JAANPR75F97100036
716	JAANPR75F97100037
717	JAANPR75F97100038
718	JAANPR75F97100039
719	JAANPR75F97100040
720	JAANPR75F97100044
721	JAANPR75F97100045
722	JAANPR75F97100046
723	JAANPR75F97100047
724	JAANPR75F97100048
725	JAANPR75F97100049
726	JAANPR75F97100050
727	JAANPR75H87100075
728	JAANPR75H87100415
729	JAANPR75H87100425
730	JAANPR75H87100431
731	JAANPR75H87100445

732	JAANPR75H87100468
733	JAANPR75H87100476
734	JAANPR75H87100483
735	JAANPR75H87100491
736	JAANPR75H87100498
737	JAANPR75H87100503
738	JAANPR75H87100536
739	JAANPR75H87100539
740	JAANPR75H87100582
741	JAANPR75H87100583
742	JAANPR75H87100598
743	JAANPR75H87100600
744	JAANPR75H87100602
745	JAANPR75H87100603
746	JAANPR75H87100606
747	JAANPR75H87100607
748	JAANPR75H87100608
749	JAANPR75H87100611
750	JAANPR75H87100613
751	JAANPR75H87100616
752	JAANPR75H87100660
753	JAANPR75H87100662
754	JAANPR75H87100664
755	JAANPR75H87100666
756	JAANPR75H87100672
757	JAANPR75H87100723
758	JAANPR75H87100725
759	JAANPR75H87100729
760	JAANPR75H87100731
761	JAANPR75H87100736
762	JAANPR75H87100738
763	JAANPR75H87100753
764	JAANPR75H87100756
765	JAANPR75H87100762
766	JAANPR75H87100790

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

767	JAANPR75H87100801	802	JAANPR75H87101319
768	JAANPR75H87100808	803	JAANPR75H87101323
769	JAANPR75H87100976	804	JAANPR75H87101324
770	JAANPR75H87100977	805	JAANPR75H87101329
771	JAANPR75H87100984	806	JAANPR75H87101334
772	JAANPR75H87100985	807	JAANPR75H87101357
773	JAANPR75H87100990	808	JAANPR75H87101358
774	JAANPR75H87100997	809	JAANPR75H87101363
775	JAANPR75H87100998	810	JAANPR75H87101364
776	JAANPR75H87101001	811	JAANPR75H87101365
777	JAANPR75H87101008	812	JAANPR75H87101372
778	JAANPR75H87101009	813	JAANPR75H87101373
779	JAANPR75H87101048	814	JAANPR75H87101374
780	JAANPR75H87101050	815	JAANPR75H87101377
781	JAANPR75H87101053	816	JAANPR75H87101378
782	JAANPR75H87101054	817	JAANPR75H87101384
783	JAANPR75H87101056	818	JAANPR75H87101385
784	JAANPR75H87101057	819	JAANPR75H87101386
785	JAANPR75H87101059	820	JAANPR75H87101390
786	JAANPR75H87101060	821	JAANPR75H87101465
787	JAANPR75H87101061	822	JAANPR75H87101474
788	JAANPR75H87101063	823	JAANPR75H87101485
789	JAANPR75H87101077	824	JAANPR75H87101494
790	JAANPR75H87101080	825	JAANPR75H87101548
791	JAANPR75H87101085	826	JAANPR75H87101558
792	JAANPR75H87101087	827	JAANPR75H87101564
793	JAANPR75H87101090	828	JAANPR75H87101569
794	JAANPR75H87101143	829	JAANPR75H87101570
795	JAANPR75H87101295	830	JAANPR75H87101601
796	JAANPR75H87101303	831	JAANPR75H87101605
797	JAANPR75H87101304	832	JAANPR75H87101606
798	JAANPR75H87101308	833	JAANPR75H87101607
799	JAANPR75H87101309	834	JAANPR75H87101609
800	JAANPR75H87101314	835	JAANPR75H87101610
801	JAANPR75H87101315	836	JAANPR75H87101611

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

837	JAANPR75H87101615
838	JAANPR75H87101616
839	JAANPR75H87101618
840	JAANPR75H87101619
841	JAANPR75H87101620
842	JAANPR75H87101621
843	JAANPR75H87101625
844	JAANPR75H87101626
845	JAANPR75H87101660
846	JAANPR75H87101669
847	JAANPR75H87101671
848	JAANPR75H87101679
849	JAANPR75H87101681
850	JAANPR75H87101688
851	JAANPR75H87101696
852	JAANPR75H87101698
853	JAANPR75H87101700
854	JAANPR75H87101701
855	JAANPR75H87101702
856	JAANPR75H87101836
857	JAANPR75H87101837
858	JAANPR75H87101838
859	JAANPR75H87101840
860	JAANPR75H87101844
861	JAANPR75H87101847
862	JAANPR75H87101848
863	JAANPR75H87101849
864	JAANPR75H87101851
865	JAANPR75H87101853
866	JAANPR75H87101854
867	JAANPR75H87101855
868	JAANPR75H87101858
869	JAANPR75H87101859
870	JAANPR75H87101860
871	JAANPR75H87101864

872	JAANPR75H87101865
873	JAANPR75H87101866
874	JAANPR75H87101867
875	JAANPR75H87101868
876	JAANPR75H87101869
877	JAANPR75H87101870
878	JAANPR75H87101871
879	JAANPR75H87101874
880	JAANPR75H87101875
881	JAANPR75H87101876
882	JAANPR75H87101877
883	JAANPR75H87101878
884	JAANPR75H87101879
885	JAANPR75H87101886
886	JAANPR75H87101887
887	JAANPR75H87101888
888	JAANPR75H87101889
889	JAANPR75H87101890
890	JAANPR75H87101891
891	JAANPR75H87101892
892	JAANPR75H87101893
893	JAANPR75H87101894
894	JAANPR75H87101895
895	JAANPR75H87101899
896	JAANPR75H87101900
897	JAANPR75H87101901
898	JAANPR75H87101902
899	JAANPR75H87101903
900	JAANPR75H87101904
901	JAANPR75H87101905
902	JAANPR75H87101906
903	JAANPR75H87101907
904	JAANPR75H87101911
905	JAANPR75H87101912
906	JAANPR75H87101913

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

907	JAANPR75H87101920
908	JAANPR75H87101921
909	JAANPR75H87101922
910	JAANPR75H87101984
911	JAANPR75H87101987
912	JAANPR75H87101988
913	JAANPR75H87101995
914	JAANPR75H87101999
915	JAANPR75H87102001
916	JAANPR75H87102003
917	JAANPR75H87102005
918	JAANPR75H87102007
919	JAANPR75H87102008
920	JAANPR75H87102009
921	JAANPR75H87102010
922	JAANPR75H87102014
923	JAANPR75H87102015
924	JAANPR75H87102016
925	JAANPR75H87102017
926	JAANPR75H87102018
927	JAANPR75H87102024
928	JAANPR75H87102029
929	JAANPR75H87102031
930	JAANPR75H87102032
931	JAANPR75H87102037
932	JAANPR75H87102038
933	JAANPR75H87102039
934	JAANPR75H87102041
935	JAANPR75H87102042
936	JAANPR75H87102043
937	JAANPR75H87102045
938	JAANPR75H87102047
939	JAANPR75H87102048
940	JAANPR75H87102049
941	JAANPR75H87102050

942	JAANPR75H87102052
943	JAANPR75H87102054
944	JAANPR75H87102055
945	JAANPR75H87102056
946	JAANPR75H87102057
947	JAANPR75H87102059
948	JAANPR75H87102062
949	JAANPR75H87102097
950	JAANPR75H87102098
951	JAANPR75H87102105
952	JAANPR75H87102106
953	JAANPR75H87102107
954	JAANPR75H87102108
955	JAANPR75H87102109
956	JAANPR75H87102110
957	JAANPR75H87102115
958	JAANPR75H87102117
959	JAANPR75H87102129
960	JAANPR75H87102130
961	JAANPR75H87102131
962	JAANPR75H87102132
963	JAANPR75H87102133
964	JAANPR75H87102177
965	JAANPR75H87102178
966	JAANPR75H87102179
967	JAANPR75H87102180
968	JAANPR75H87102181
969	JAANPR75H87102182
970	JAANPR75H87102183
971	JAANPR75H87102200
972	JAANPR75H87102209
973	JAANPR75H87102210
974	JAANPR75H87102211
975	JAANPR75H87102212
976	JAANPR75H87102213

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

977	JAANPR75H87102214	1012	JAANPR75H87102487
978	JAANPR75H87102215	1013	JAANPR75H87102488
979	JAANPR75H87102216	1014	JAANPR75H87102496
980	JAANPR75H87102217	1015	JAANPR75H87102497
981	JAANPR75H87102218	1016	JAANPR75H87102498
982	JAANPR75H87102237	1017	JAANPR75H97101250
983	JAANPR75H87102244	1018	JAANPR75H97101613
984	JAANPR75H87102250	1019	JAANPR75H97101614
985	JAANPR75H87102252	1020	JAANPR75H97101615
986	JAANPR75H87102256	1021	JAANPR75H97101616
987	JAANPR75H87102265	1022	JAANPR75H97101617
988	JAANPR75H87102269	1023	JAANPR75H97101618
989	JAANPR75H87102287	1024	JAANPR75H97101619
990	JAANPR75H87102288	1025	JAANPR75H97101656
991	JAANPR75H87102320	1026	JAANPR75H97101658
992	JAANPR75H87102326	1027	JAANPR75H97101659
993	JAANPR75H87102330	1028	JAANPR75H97101660
994	JAANPR75H87102333	1029	JAANPR75H97101661
995	JAANPR75H87102336	1030	JAANPR75H97101662
996	JAANPR75H87102411	1031	JAANPR75H97101663
997	JAANPR75H87102413	1032	JAANPR75H97101664
998	JAANPR75H87102416	1033	JAANPR75H97101850
999	JAANPR75H87102419	1034	JAANPR75H97101851
1000	JAANPR75H87102420	1035	JAANPR75H97101852
1001	JAANPR75H87102439	1036	JAANPR75H97101853
1002	JAANPR75H87102440	1037	JAANPR75H97101854
1003	JAANPR75H87102461	1038	JAANPR75H97101855
1004	JAANPR75H87102471	1039	JAANPR75H97101856
1005	JAANPR75H87102472	1040	JAANPR75H97101857
1006	JAANPR75H87102476	1041	JAANPR75H97101858
1007	JAANPR75H87102477	1042	JAANPR75H97101859
1008	JAANPR75H87102478	1043	JAANPR75H97101860
1009	JAANPR75H87102479	1044	JAANPR75H97101861
1010	JAANPR75H87102480	1045	JAANPR75H97101863
1011	JAANPR75H87102481	1046	JAANPR75H97101864

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1047	JAANPR75H97101865
1048	JAANPR75H97101868
1049	JAANPR75H97101869
1050	JAANPR75H97101870
1051	JAANPR75H97101873
1052	JAANPR75H97101875
1053	JAANPR75H97101879
1054	JAANPR75H97101887
1055	JAANPR75H97101888
1056	JAANPR75H97101889
1057	JAANPR75H97101890
1058	JAANPR75H97101891
1059	JAANPR75H97101892
1060	JAANPR75H97101893
1061	JAANPR75H97101894
1062	JAANPR75H97101895
1063	JAANPR75H97101896
1064	JAANPR75H97101897
1065	JAANPR75H97101898
1066	JAANPR75H97101899
1067	JAANPR75H97101900
1068	JAANPR75H97101901
1069	JAANPR75H97101902
1070	JAANPR75H97101903
1071	JAANPR75H97101906
1072	JAANPR75H97101909
1073	JAANPR75H97101913
1074	JAANPR75H97101917
1075	JAANPR75H97101920
1076	JAANPR75H97101928
1077	JAANPR75H97101929
1078	JAANPR75H97101930
1079	JAANPR75H97101931
1080	JAANPR75H97101932
1081	JAANPR75H97101933

1082	JAANPR75H97101934
1083	JAANPR75H97101935
1084	JAANPR75H97101936
1085	JAANPR75H97101937
1086	JAANPR75H97101938
1087	JAANPR75H97101939
1088	JAANPR75H97101940
1089	JAANPR75H97101941
1090	JAANPR75H97101942
1091	JAANPR75H97101943
1092	JAANPR75H97101944
1093	JAANPR75H97101945
1094	JAANPR75H97101946
1095	JAANPR75H97101947
1096	JAANPR75H97101948
1097	JAANPR75H97101949
1098	JAANPR75K87100020
1099	JAANPR75K87100021
1100	JAANPR75K87100022
1101	JAANPR75K87100023
1102	JAANPR75K87100024
1103	JAANPR75K87100025
1104	JAANPR75K87100028
1105	JAANPR75K87100030
1106	JAANPR75K87100031
1107	JAANPR75K87100034
1108	JAANPR75K87100036
1109	JAANPR75K87100037
1110	JAANPR75K87100052
1111	JAANPR75K87100057
1112	JAANPR75K87100058
1113	JAANPR75K87100059
1114	JAANPR75K87100060
1115	JAANPR75K87100061
1116	JAANPR75K87100062

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1117	JAANPR75K87100063
1118	JAANPR75K87100064
1119	JAANPR75K87100065
1120	JAANPR75K87100066
1121	JAANPR75K87100067
1122	JAANPR75K87100068
1123	JAANPR75K87100069
1124	JAANPR75K87100070
1125	JAANPR75K87100071
1126	JAANPR75K87100072
1127	JAANPR75K87100073
1128	JAANPR75K87100074
1129	JAANPR75K87100075
1130	JAANPR75K87100076
1131	JAANPR75K87100077
1132	JAANPR75K87100078
1133	JAANPR75K87100079
1134	JAANPR75K87100080
1135	JAANPR75K87100081
1136	JAANPR75K87100082
1137	JAANPR75K87100083
1138	JAANPR75K87100084
1139	JAANPR75K87100085
1140	JAANPR75K87100086
1141	JAANPR75K87100088
1142	JAANPR75K87100090
1143	JAANPR75K87100093
1144	JAANPR75K87100095
1145	JAANPR75K87100096
1146	JAANPR75K87100097
1147	JAANPR75K87100098
1148	JAANPR75K87100099
1149	JAANPR75K87100100
1150	JAANPR75K87100101
1151	JAANPR75K87100102

1152	JAANPR75K87100103
1153	JAANPR75K87100104
1154	JAANPR75K87100105
1155	JAANPR75K87100106
1156	JAANPR75K87100107
1157	JAANPR75K87100108
1158	JAANPR75K87100114
1159	JAANPR75K87100115
1160	JAANPR75K87100116
1161	JAANPR75K87100118
1162	JAANPR75K87100120
1163	JAANPR75K87100122
1164	JAANPR75K87100125
1165	JAANPR75K87100126
1166	JAANPR75K87100129
1167	JAANPR75K87100131
1168	JAANPR75K87100132
1169	JAANPR75K87100133
1170	JAANPR75K87100134
1171	JAANPR75K87100135
1172	JAANPR75K87100138
1173	JAANPR75K87100145
1174	JAANPR75K87100146
1175	JAANPR75K87100147
1176	JAANPR75K87100148
1177	JAANPR75K87100149
1178	JAANPR75K87100150
1179	JAANPR75K87100151
1180	JAANPR75K87100152
1181	JAANPR75K87100154
1182	JAANPR75K87100160
1183	JAANPR75K87100162
1184	JAANPR75K87100164
1185	JAANPR75K87100165
1186	JAANPR75K87100166

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1187	JAANPR75K87100167
1188	JAANPR75K87100168
1189	JAANPR75K87100169
1190	JAANPR75K87100170
1191	JAANPR75K87100171
1192	JAANPR75K87100172
1193	JAANPR75K87100173
1194	JAANPR75K87100174
1195	JAANPR75K87100175
1196	JAANPR75K87100176
1197	JAANPR75K87100177
1198	JAANPR75K87100178
1199	JAANPR75K87100192
1200	JAANPR75K87100194
1201	JAANPR75K87100196
1202	JAANPR75K87100197
1203	JAANPR75K87100198
1204	JAANPR75K87100199
1205	JAANPR75K87100200
1206	JAANPR75K87100214
1207	JAANPR75K87100216
1208	JAANPR75K87100217
1209	JAANPR75K87100219
1210	JAANPR75K87100220
1211	JAANPR75K87100221
1212	JAANPR75K87100222
1213	JAANPR75K87100223
1214	JAANPR75K87100224
1215	JAANPR75K87100225
1216	JAANPR75K87100226
1217	JAANPR75K87100227
1218	JAANPR75K87100228
1219	JAANPR75K87100229
1220	JAANPR75K87100245
1221	JAANPR75K87100246

1222	JAANPR75K87100247
1223	JAANPR75K87100248
1224	JAANPR75K87100249
1225	JAANPR75K87100268
1226	JAANPR75K87100270
1227	JAANPR75K87100272
1228	JAANPR75K87100274
1229	JAANPR75K87100275
1230	JAANPR75K87100276
1231	JAANPR75K87100278
1232	JAANPR75K87100279
1233	JAANPR75K87100281
1234	JAANPR75K87100282
1235	JAANPR75K87100283
1236	JAANPR75K87100284
1237	JAANPR75K87100285
1238	JAANPR75K87100286
1239	JAANPR75K87100287
1240	JAANPR75K87100288
1241	JAANPR75K87100289
1242	JAANPR75K87100290
1243	JAANPR75K87100291
1244	JAANPR75K87100293
1245	JAANPR75K87100296
1246	JAANPR75K87100301
1247	JAANPR75K87100304
1248	JAANPR75K87100339
1249	JAANPR75K87100341
1250	JAANPR75K87100348
1251	JAANPR75K87100355
1252	JAANPR75K87100356
1253	JAANPR75K87100358
1254	JAANPR75K87100383
1255	JAANPR75K87100384
1256	JAANPR75K87100385

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1257	JAANPR75K87100386	1292	JAANPR75K87100543
1258	JAANPR75K87100387	1293	JAANPR75K87100546
1259	JAANPR75K87100388	1294	JAANPR75K87100547
1260	JAANPR75K87100389	1295	JAANPR75K87100548
1261	JAANPR75K87100390	1296	JAANPR75K87100549
1262	JAANPR75K87100391	1297	JAANPR75K87100550
1263	JAANPR75K87100392	1298	JAANPR75K87100551
1264	JAANPR75K87100393	1299	JAANPR75K87100552
1265	JAANPR75K87100394	1300	JAANPR75K87100553
1266	JAANPR75K87100395	1301	JAANPR75K87100554
1267	JAANPR75K87100396	1302	JAANPR75K87100555
1268	JAANPR75K87100397	1303	JAANPR75K87100557
1269	JAANPR75K87100398	1304	JAANPR75K87100558
1270	JAANPR75K87100399	1305	JAANPR75K87100559
1271	JAANPR75K87100400	1306	JAANPR75K87100560
1272	JAANPR75K87100401	1307	JAANPR75K87100561
1273	JAANPR75K87100402	1308	JAANPR75K87100562
1274	JAANPR75K87100403	1309	JAANPR75K87100563
1275	JAANPR75K87100404	1310	JAANPR75K87100564
1276	JAANPR75K87100405	1311	JAANPR75K87100565
1277	JAANPR75K87100406	1312	JAANPR75K87100566
1278	JAANPR75K87100407	1313	JAANPR75K87100567
1279	JAANPR75K87100408	1314	JAANPR75K87100568
1280	JAANPR75K87100409	1315	JAANPR75K87100569
1281	JAANPR75K87100410	1316	JAANPR75K87100618
1282	JAANPR75K87100411	1317	JAANPR75K87100619
1283	JAANPR75K87100412	1318	JAANPR75K87100620
1284	JAANPR75K87100413	1319	JAANPR75K87100621
1285	JAANPR75K87100414	1320	JAANPR75K87100622
1286	JAANPR75K87100415	1321	JAANPR75K87100623
1287	JAANPR75K87100442	1322	JAANPR75K87100624
1288	JAANPR75K87100444	1323	JAANPR75K87100625
1289	JAANPR75K87100447	1324	JAANPR75K87100626
1290	JAANPR75K87100448	1325	JAANPR75K87100627
1291	JAANPR75K87100541	1326	JAANPR75K87100711

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1327	JAANPR75K87100712	1362	JAANPR75K87100765
1328	JAANPR75K87100713	1363	JAANPR75K87100766
1329	JAANPR75K87100714	1364	JAANPR75K87100767
1330	JAANPR75K87100715	1365	JAANPR75K87100768
1331	JAANPR75K87100716	1366	JAANPR75K87100769
1332	JAANPR75K87100717	1367	JAANPR75K87100770
1333	JAANPR75K87100718	1368	JAANPR75K87100771
1334	JAANPR75K87100719	1369	JAANPR75K87100772
1335	JAANPR75K87100720	1370	JAANPR75K87100773
1336	JAANPR75K87100721	1371	JAANPR75K87100774
1337	JAANPR75K87100722	1372	JAANPR75K87100775
1338	JAANPR75K87100723	1373	JAANPR75K87100776
1339	JAANPR75K87100724	1374	JAANPR75K87100777
1340	JAANPR75K87100725	1375	JAANPR75K87100796
1341	JAANPR75K87100726	1376	JAANPR75K87100797
1342	JAANPR75K87100727	1377	JAANPR75K87100798
1343	JAANPR75K87100728	1378	JAANPR75K87100799
1344	JAANPR75K87100729	1379	JAANPR75K87100800
1345	JAANPR75K87100730	1380	JAANPR75K87100801
1346	JAANPR75K87100731	1381	JAANPR75K87100802
1347	JAANPR75K87100732	1382	JAANPR75K87100803
1348	JAANPR75K87100733	1383	JAANPR75K87100804
1349	JAANPR75K87100734	1384	JAANPR75K87100805
1350	JAANPR75K87100735	1385	JAANPR75K87100878
1351	JAANPR75K87100736	1386	JAANPR75K87100879
1352	JAANPR75K87100737	1387	JAANPR75K87100880
1353	JAANPR75K87100756	1388	JAANPR75K87100881
1354	JAANPR75K87100757	1389	JAANPR75K87100882
1355	JAANPR75K87100758	1390	JAANPR75K87100883
1356	JAANPR75K87100759	1391	JAANPR75K87100884
1357	JAANPR75K87100760	1392	JAANPR75K87100885
1358	JAANPR75K87100761	1393	JAANPR75K87100886
1359	JAANPR75K87100762	1394	JAANPR75K87100887
1360	JAANPR75K87100763	1395	JAANPR75K87100888
1361	JAANPR75K87100764	1396	JAANPR75K87100889

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1397	JAANPR75K87100890
1398	JAANPR75K87100891
1399	JAANPR75K87100892
1400	JAANPR75K87100925
1401	JAANPR75K87100926
1402	JAANPR75K87100927
1403	JAANPR75K87100928
1404	JAANPR75K87100929
1405	JAANPR75K87100930
1406	JAANPR75K87100931
1407	JAANPR75K87100932
1408	JAANPR75K87100933
1409	JAANPR75K87100934
1410	JAANPR75K87100935
1411	JAANPR75K87100936
1412	JAANPR75K87100937
1413	JAANPR75K87100938
1414	JAANPR75K87100939
1415	JAANPR75K87100940
1416	JAANPR75K87100941
1417	JAANPR75K87100942
1418	JAANPR75K87100943
1419	JAANPR75K87100944
1420	JAANPR75K87100945
1421	JAANPR75K87100946
1422	JAANPR75K87100947
1423	JAANPR75K87100948
1424	JAANPR75K87100949
1425	JAANPR75K87100950
1426	JAANPR75K87100951
1427	JAANPR75K87100952
1428	JAANPR75K87100953
1429	JAANPR75K87100960
1430	JAANPR75K87100961
1431	JAANPR75K87100962

1432	JAANPR75K87100963
1433	JAANPR75K87100964
1434	JAANPR75K87100965
1435	JAANPR75K87100966
1436	JAANPR75K87100967
1437	JAANPR75K87100968
1438	JAANPR75K87100969
1439	JAANPR75K87100970
1440	JAANPR75K87100971
1441	JAANPR75K87101014
1442	JAANPR75K87101015
1443	JAANPR75K87101018
1444	JAANPR75K87101022
1445	JAANPR75K87101023
1446	JAANPR75K87101024
1447	JAANPR75K87101025
1448	JAANPR75K87101026
1449	JAANPR75K87101028
1450	JAANPR75K87101029
1451	JAANPR75K87101030
1452	JAANPR75K87101031
1453	JAANPR75K87101032
1454	JAANPR75K87101034
1455	JAANPR75K87101035
1456	JAANPR75K87101036
1457	JAANPR75K87101037
1458	JAANPR75K87101038
1459	JAANPR75K87101039
1460	JAANPR75K87101040
1461	JAANPR75K87101041
1462	JAANPR75K87101042
1463	JAANPR75K87101043
1464	JAANPR75K87101044
1465	JAANPR75K87101045
1466	JAANPR75K87101046

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1467	JAANPR75K87101047	1502	JAANPR75K87101106
1468	JAANPR75K87101048	1503	JAANPR75K87101107
1469	JAANPR75K87101049	1504	JAANPR75K87101108
1470	JAANPR75K87101050	1505	JAANPR75K87101109
1471	JAANPR75K87101051	1506	JAANPR75K87101110
1472	JAANPR75K87101052	1507	JAANPR75K87101111
1473	JAANPR75K87101053	1508	JAANPR75K87101112
1474	JAANPR75K87101054	1509	JAANPR75K87101113
1475	JAANPR75K87101055	1510	JAANPR75K87101114
1476	JAANPR75K87101056	1511	JAANPR75K87101115
1477	JAANPR75K87101057	1512	JAANPR75K87101116
1478	JAANPR75K87101058	1513	JAANPR75K87101117
1479	JAANPR75K87101059	1514	JAANPR75K87101118
1480	JAANPR75K87101060	1515	JAANPR75K87101119
1481	JAANPR75K87101061	1516	JAANPR75K97100490
1482	JAANPR75K87101062	1517	JAANPR75K97100593
1483	JAANPR75K87101063	1518	JAANPR75K97100684
1484	JAANPR75K87101064	1519	JAANPR75K97100685
1485	JAANPR75K87101065	1520	JAANPR75K97100686
1486	JAANPR75K87101066	1521	JAANPR75K97100687
1487	JAANPR75K87101085	1522	JAANPR75K97100766
1488	JAANPR75K87101086	1523	JAANPR75K97100767
1489	JAANPR75K87101087	1524	JAANPR75K97100768
1490	JAANPR75K87101088	1525	JAANPR75K97100769
1491	JAANPR75K87101089	1526	JAANPR75K97100770
1492	JAANPR75K87101090	1527	JAANPR75K97100832
1493	JAANPR75K87101091	1528	JAANPR75K97100925
1494	JAANPR75K87101092	1529	JAANPR75K97100927
1495	JAANPR75K87101093	1530	JAANPR75K97100929
1496	JAANPR75K87101094	1531	JAANPR75K97100931
1497	JAANPR75K87101095	1532	JAANPR75K97100933
1498	JAANPR75K87101096	1533	JAANPR75K97100935
1499	JAANPR75K87101097	1534	JAANPR75K97100937
1500	JAANPR75K87101098	1535	JAANPR75K97100939
1501	JAANPR75K87101099	1536	JAANPR75K97100941

車輛安全召回資訊

Vehicle Safety Recall Information

10000316

製造商 Make: ISUZU 五十鈴

型號 Model: 08MY F-Series / 07-08MY N-Series

項目 Subject: 響號按鈕電線改良運動

Horn Harness Routing Change

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

1537	JAANPR75K97101011
1538	JAANPR75K97101013
1539	JAANPR75K97101016
1540	JAANPR75K97101021
1541	JAANPR75K97101023
1542	JAANPR75K97101098
1543	JAANPR75K97101099
1544	JAANPR75K97101100
1545	JAANPR75K97101101
1546	JAANPR75K97101102
1547	JAANPR75K97101103
1548	JAANPR75K97101105
1549	JAANPR75K97101106
1550	JAANPR75K97101107
1551	JAANPR75K97101108
1552	JAANPR75K97101109
1553	JAANPR75K97101110
1554	JAANPR75K97101111
1555	JAANPR75K97101112
1556	JAANPR75K97101113
1557	JAANPR75K97101114
1558	JAANPR75K97101115
1559	JAANPR75K97101116
1560	JAANPR75K97101117

1561	JAANPR75K97101118
1562	JAANPR75K97101157
1563	JAANPR75K97101158
1564	JAANPR75K97101523
1565	JAANPR75K97101524
1566	JAANPR75K97101525
1567	JAANPR75K97101526
1568	JAANPR75K97101527
1569	JAANPR75K97101528
1570	JAANPR75K97101529
1571	JAANPR75K97101530
1572	JAANPR75K97101531
1573	JAANPR75K97101532
1574	JAANPR75K97101533
1575	JAANPR75K97101534
1576	JAANPR75K97101535
1577	JAANPR75K97101536
1578	JAANPR75K97101537
1579	JAANPR75K97101538
1580	JAANPR75K97101539
1581	JAANPR75L77100042
1582	JAANPR75L77100393
1583	JAANPR75L77100394
1584	JAANPR75P87100170