

車輛安全召回資訊

Vehicle Safety Recall Information

10000279

製造商 Make: 鈴木汽車公司 SUZUKI

型 號 Model: GSX-R1000K5 / K6

項 目 Subject: 車架檢查 / 強化支柱加裝

Frame inspection and installation of a frame reinforcement brace

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

	VIN	MODEL
1	JS1B6111200101018	GSX-R1000K5
2	JS1B6111200101019	GSX-R1000K5
3	JS1B6111200101020	GSX-R1000K5
4	JS1B6111200101024	GSX-R1000K5
5	JS1B6111200101884	GSX-R1000K5
6	JS1B6111200101887	GSX-R1000K5
7	JS1B6111200101903	GSX-R1000K6
8	JS1B6111200102015	GSX-R1000K6
9	JS1B6111200102019	GSX-R1000K6
10	JS1B6111200102020	GSX-R1000K6
11	JS1B6111200102059	GSX-R1000K6
12	JS1B6111200102060	GSX-R1000K6
13	JS1B6111200102159	GSX-R1000K6
14	JS1B6111200102160	GSX-R1000K6
15	JS1B6111200102166	GSX-R1000K6
16	JS1B6111200102373	GSX-R1000K6
17	JS1B6111200102374	GSX-R1000K6
18	JS1B6111200102677	GSX-R1000K6
19	JS1B6111200102755	GSX-R1000K6
20	JS1B6111200102757	GSX-R1000K6
21	JS1B6111200103081	GSX-R1000K6
22	JS1B6111200103083	GSX-R1000K6
23	JS1B6111200103122	GSX-R1000K6
24	JS1B6111200103319	GSX-R1000K6
25	JS1B6111200103328	GSX-R1000K6
26	JS1B6111200103361	GSX-R1000K6
27	JS1B6111200103433	GSX-R1000K6