

# 車輛安全召回資訊

## Vehicle Safety Recall Information

10000297

製造商 Make: 奧迪 Audi

型號 Model: A3 2.0T (8P) & TT 2.0T (8J)

項目 Subject: 波箱電腦軟體更新

Software update for gearbox control unit

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

1	<b>TRUZZZ8J291017667</b>
2	<b>TRUZZZ8J491017685</b>
3	<b>TRUZZZ8J091017988</b>
4	<b>TRUZZZ8J791018541</b>
5	<b>TRUZZZ8J691018868</b>
6	<b>TRUZZZ8JX91019067</b>
7	<b>TRUZZZ8J591019168</b>
8	<b>TRUZZZ8J391021288</b>
9	<b>TRUZZZ8J891021576</b>

10	<b>TRUZZZ8J191022150</b>
11	<b>TRUZZZ8J591023284</b>
12	<b>TRUZZZ8J191023878</b>
13	<b>TRUZZZ8J491024006</b>
14	<b>TRUZZZ8J191024156</b>
15	<b>TRUZZZ8J991024177</b>
16	<b>TRUZZZ8JX91024267</b>
17	<b>TRUZZZ8J691024525</b>